





report date: 2024-03-29

General information

Make	VOLVO
Model	V40 T2 MOMENTUM
Colour	Black
Year of manufacture	2018
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	220 Nm at 1.200 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Petrol
Consumption combined	2.8 mpg
CO2 emission	137 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

_		•		_	-
-	n	т	rv	,	

Date	2022-02-16
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT I	nistory
-------	---------

MOT expiry date	2025-02-14
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	4
Total items failed	2

MOT #5	2024-02-06 11:18
MOT test number	560670910653
Result	✓ Passed
Next expiry date	2025-02-14
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #4	2023-02-02 14:42
MOT test number	922452593720
Result	✓ Passed

MOT #3	2023-02-02 11:21
MOT test number	909364405772
Result	🗙 Failed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	

MOT #2	2022-02-15 08:32
MOT test number	513441569435
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	14 February 2025
Full MOT history	See MOT history

Tax calculation

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

More info >

Owner history	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	NK AIN
Plate since	

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-08-30
Last registration	2024-02-06
Complete history	See info



Registration #1	2018-08-30	19 mi
Registration #2	2021-08-04	20.092 mi
Registration #3	2022-02-15	22.247 mi
Registration #4		71.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11,177 mi

More info >

CarCheck.co.uk page 10/11



BW18PVO report date: 2024-03-29

Car features

50225	Air conditionin
50295	
50482	
50501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	1857 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1393 kg
Max. allowed weight	1965 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/2

Number of axles 2

Engine number 2630091