



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO SE TSI
Colour	Blue
Year of manufacture	2015
Top speed	114 mph
0 - 100 km/h	10.8 seconds
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	66 kW / 90 HP / 89 BHP
Max. torque	160 Nm at 1.400 rpm
Engine capacity	1.197 cc
Cylinders	4
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	107 g/km
CO2 label	B







Internet history

Entry 1

Date	2021-09-16
Pictures	26
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-30
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	32
Total items failed	3

MOT #8	2024-01-24 13:04
--------	------------------

MOT test number	547640588274
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-01-30
------------------	------------

- Advice** Offside Front Tyre worn close to legal limit/worn on edge Smooth on inner edge (5.2.3 (e))
- Advice** Offside Rear Brake disc worn, but not excessively Lipped (1.1.14 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Cracking in tread pattern (5.2.3 (d) (ii))
- Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing Cracking in tread pattern (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake disc worn, but not excessively Lipped (1.1.14 (a) (i))
- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Cracking in tread pattern (5.2.3 (d) (ii))

**MOT #7**

2024-01-24 10:11

MOT test number

871585031187

Result**✗ Failed**

- Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Cracking in tread pattern (5.2.3 (d) (ii))
- Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))
- Advice** Nearside Rear Brake disc worn, but not excessively Lipped (1.1.14 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing Cracking in tread pattern (5.2.3 (d) (ii))
- Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Nearside Front Service brake excessively fluctuating (1.2.1 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Cracking in tread pattern (5.2.3 (d) (ii))
- Advice** Offside Rear Brake disc worn, but not excessively Lipped (1.1.14 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Smooth on inner edge (5.2.3 (e))
- Advice** Offside Front Brake disc worn, but not excessively Heavily lipped (1.1.14 (a) (i))

MOT #6

2023-01-31 14:22

MOT test number

230894546586

Result**✓ Passed**

- Advice** Vehicles internal headlight adjuster altered to recheck lights

MOT #5

2022-03-10 16:54

MOT test number

776338395962

Result**✓ Passed**

**MOT #4** 2021-07-26 10:35**MOT test number** 276515088709**Result** ✓ Passed**MOT #3** 2020-07-31 08:46**MOT test number** 672220310977**Result** ✓ Passed

- Advice** Rear wiper blade worn
- Advice** Offside Rear tyre cracked 185/60/15 also wearing close limit
- Advice** Nearside Front tyre perished 185/60/15 also wearing inner outer edges
- Advice** Rear brake discs starting to corrode
- Advice** Front both wiper blade slight worn
- Advice** Nearside Rear tyre cracked 185/60/15 also wearing close limit
- Advice** Offside Front tyre perished 185/60/15 also wearing inner outer edges
- Advice** Front brake discs slight lipped also brake pads 50% worn

MOT #2 2019-07-26 12:32**MOT test number** 851249713307**Result** ✓ Passed

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing developing slight cracks in tread & slight perishing on outer wall (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both developing slight corrosion on edges (1.1.14 (a) (ii))
- Advice** Damage To Nearside Rear Wheel Arch.
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing developing slight cracks in tread (5.2.3 (d) (ii))
- Advice** Front Brake disc worn, but not excessively slightly worn with 'lipped' edges. (1.1.14 (a) (i))
- Advice** Front Brake pad(s) wearing thin worn to approx. 5mm (1.1.13 (a) (ii))



MOT #1	2018-07-19 13:59
MOT test number	206375387757
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
30 January 2025

Tax status	Valid until 1 October
Days left	154
MOT expiry date	30 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-07-31
Last registration	2024-01-24
Complete history	See info



Registration #1	2015-07-31	10 mi
Registration #2	2018-07-19	17.504 mi
Registration #3	2019-07-26	26.302 mi
Registration #4	2020-07-31	33.488 mi
Registration #5	2021-07-26	40.503 mi
Registration #6	2022-07-26	48.503 mi
Registration #7	2023-07-26	56.503 mi
Registration #8	2024-01-24	64.503 mi
Registration #9	2024-01-24	72.503 mi
Registration #10	2024-01-24	80.503 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1901 mm
Height	1462 mm
Length	3972 mm
Wheel base	2470 mm
Kerb weight	1007 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5

Number of axles	2
Engine number	CJZC437240