




report date: 2024-03-28

General information

Make	VOLVO
Model	V70 V70 T5 SE
Colour	Blue
Year of manufacture	2003
Top speed	155 mph
0 - 60 mph	7.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	250 BHP
Max. torque	330 Nm at 2.400 rpm
Engine capacity	2.319 cc
Cylinders	5
Fuel type	Petrol
Consumption city	21.6 mpg
Consumption extra urban	39.8 mpg
Consumption combined	30.4 mpg
CO2 emission	258 g/km
CO2 label	M





MOT history

MOT expiry date	2019-11-27
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	46
Total items failed	22

MOT #20	2018-11-12 17:23
---------	------------------

MOT test number	375461866024
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2019-11-27
------------------	------------

- Advice** Centre upper engine stabiliser mount is badly deteriorated/damaged, but is not causing excessive engine movement
- Advice** Fuel filter casing is corroded
- Advice** Nearside Front Road wheel slightly distorted inner rim dented (5.2.2 (c) (i))
- Advice** Offside front fog lamp lens is damaged
- Advice** Engine has oil leak/s. Under trays fitted, unable to determine severity
- Advice** Exhaust system is corroded and rear box metal hanger is broken
- Advice** Coil spring corroded both rear (5.3.1 (b) (i))
- Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #19**

2018-11-08 13:13

MOT test number

333630810670

Result**✗ Failed****Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Nearside Front Road wheel slightly distorted inner rim dented (5.2.2 (c) (i))**Advice** Centre upper engine stabiliser mount is badly deteriorated/damaged, but is not causing excessive engine movement**Fail** Offside Parking brake inoperative on one side (1.4.1 (a))**Advice** Fuel filter casing is corroded**Advice** Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**Advice** Coil spring corroded both rear (5.3.1 (b) (i))**Advice** Offside front fog lamp lens is damaged**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Engine has oil leak/s. Under trays fitted, unable to determine severity**Advice** Exhaust system is corroded and rear box metal hanger is broken**MOT #18**

2017-11-28 08:43

MOT test number

207296156602

Result**✓ Passed****Advice** Front tyres+offside rear tyre wearing on edges,slight play in steering,slight play in front suspension arm bushes,oil leaks**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Rear Exhaust has a minor leak of exhaust gases box+corroding (7.1.2)

**MOT #17** 2016-12-20 11:19**MOT test number** 463705697579**Result** ✓ Passed**Advice** Slight play in steering,oil leaks**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #16** 2016-12-15 15:19**MOT test number** 854796155079**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Slight play in steering,oil leaks**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside front+nearside rear tyres wearing on edges**MOT #15** 2016-01-05 12:14**MOT test number** 700335688620**Result** ✓ Passed**Advice** Off side hand brake effort low.**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Wear in inner steering rack joints.**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #14** 2015-01-05 16:48**MOT test number** 319545505089**Result** ✓ Passed**Notice** Exhaust poor condition/slight leaks

**MOT #13** 2015-01-05 14:46**MOT test number** 136165105444**Result** ✗ Failed**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Notice** Exhaust poor condition/slight leaks**MOT #12** 2013-12-09 16:22**MOT test number** 659143343392**Result** ✓ Passed**Notice** Slight play in steering+joints,slight play in front suspension arm bushes,cuts in offside front tyre**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #11** 2013-12-09 12:20**MOT test number** 578513143308**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Front Brake hose excessively deteriorated (3.6.B.4d)**Notice** Slight play in steering+joints,slight play in front suspension arm bushes,cuts in offside front tyre**Fail** Nearside Front Brake hose excessively deteriorated (3.6.B.4d)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #10** 2012-10-01 16:56**MOT test number** 989525172277**Result** ✓ Passed**Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)

**MOT #9**

2012-10-01 14:54

MOT test number

166295772261

Result

✗ Failed

Fail Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Notice** Air bag warning light on dash**Fail** Parking brake lever has no reserve travel (3.1.6b)**Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)**Fail** Nearside Outer Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)**MOT #8**

2011-09-22 14:25

MOT test number

408245961232

Result

✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7**

2011-09-21 12:21

MOT test number

997724061283

Result

✗ Failed

Fail Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Headlamp aim too low (1.8)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**MOT #6** 2010-08-26 09:41**MOT test number** 303928530458**Result** ✓ Passed**MOT #5** 2009-09-09 15:18**MOT test number** 752622559238**Result** ✓ Passed**MOT #4** 2008-09-10 14:49**MOT test number** 484744358254**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2008-09-10 14:49**MOT test number** 943954058294**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2007-09-06 15:31**MOT test number** 171499647282**Result** ✓ Passed**MOT #1** 2006-09-11 08:53**MOT test number** 471044756200**Result** ✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2003-09-09
Last registration	2018-11-12
Complete history	See info



Registration #1	2003-09-09	21 mi
Registration #2	2006-09-11	38.446 mi
Registration #3	2007-09-06	48.851 mi
Registration #4	2008-09-10	57.671 mi
Registration #5	2009-09-09	67.613 mi
Registration #6	2010-08-26	77.617 mi
Registration #7	2011-09-21	90.629 mi
Registration #8	2011-09-22	90.634 mi
Registration #9	2012-10-01	104.414 mi
Registration #10	2012-10-01	104.414 mi
Registration #11	2013-09-09	114.414 mi
Registration #12	2014-09-09	124.414 mi
Registration #13	2015-09-09	134.414 mi
Registration #14	2016-09-09	144.414 mi
Registration #15	2017-09-09	154.414 mi
Registration #16	2018-09-09	164.414 mi
Registration #17	2019-09-09	174.414 mi
Registration #18	2020-09-09	184.414 mi
Registration #19	2021-09-09	194.414 mi
Registration #20	2022-09-09	204.414 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1720 mm
Height	1400 mm
Length	4520 mm
Wheel base	2560 mm
Kerb weight	1560 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	B5234T2931895