





report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	GLA GLA 200 D AMG LINE EXECUTIVE
Colour	White
Year of manufacture	2017
Top speed	127 mph
0 - 100 km/h	7.7 seconds
0 - 60 mph	9.1 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	130 kW / 177 HP / 134 BHP
Max. torque	350 Nm at 1.400 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date	2021-02-02
Pictures	1
Listing price	<u>View report</u>



source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-04-22
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	12
Total items failed	3

MOT #7	2024-04-08 11:50
MOT test number	845400121494
Result	✓ Passed
Next expiry date	2025-04-22
Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	

MOT #6	2023-04-22 14:27
MOT test number	848253697147
Result	✓ Passed

Result	✓ Passed
MOT #5	2022-04-22 10:26
MOT test number	647797852218
Result	✓ Passed
Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely det	eriorated (6.1.7 (g) (i))

MOT #4	2021-04-23 12:01
MOT test number	497943244910
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #3 2020-09-19 11:00

MOT test number 646194087579

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #2 2020-09-19 10:07

MOT test number 253784321593

Result X Failed

Fail Nearside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2020-05-15 06:10

MOT test number 428393708279

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	22 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



More info >

Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Do report here .	

Plate changes	More info >
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	NK NY
Plate since	
Current registration	NK NY
Plate since	

CarCheck.co.uk page 8/11



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



KP17DXZ

report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-05-23
Last registration	2024-04-08
Complete history	See info



Registration #1	2017-05-23	29 mi
Registration #2	2020-09-19	37.719 mi
Registration #3	2020-09-19	37.719 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
0567	
60569	
iew the complete MERCEDES-BENZ factory list for this	More info >

\neg	imer		(ᅩ
		חשו	ns 1	V 1/1/	reirei	

Width	1804 mm
Height	1494 mm
Length	4424 mm
Wheel base	2699 mm
Kerb weight	1535 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	65193034347174

CarCheck.co.uk page 11/11