



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA SRI + CDTI 150
Colour	Silver
Year of manufacture	-
Top speed	129 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	315 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	48.7 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-08
Pictures	14
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #20	2022-04-16 14:53
MOT test number	162232752594
Result	✓ Passed
Next expiry date	2023-04-15
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Exhaust system corroded, front flexi slightly leaking.
Advice	Rear Anti-roll bar corroded but not seriously weakened n/s & o/s (5.3.3 (b) (i))
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Brake disc worn, pitted or scored, but not seriously weakened front & rear (1.1.14 (a) (ii))
Advice	Rear Coil spring corroded both sides (5.3.1 (b) (i))
Advice	Under-trays fitted.
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.2.2 (a) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #19	2021-03-09 16:08
MOT test number	301253677309
Result	✓ Passed

MOT #18	2020-03-02 09:12
MOT test number	607906719207
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #17** 2020-02-27 12:05**MOT test number** 984315830504**Result** ✗ Failed**Fail** Nearside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))**Fail** Nearside Rear Anti-roll bar pin or bush excessively worn d bush (5.3.4 (a) (i))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Offside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Anti-roll bar pin or bush excessively worn d bush (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #16** 2019-03-28 09:57**MOT test number** 962489765916**Result** ✓ Passed**MOT #15** 2018-03-08 09:21**MOT test number** 749780770638**Result** ✓ Passed**Advice** Oil leak**Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #14**

2018-03-07 10:25

MOT test number

517717495082

Result**✗ Failed****Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Oil leak**MOT #13**

2017-03-03 11:32

MOT test number

394444396473

Result**✓ Passed****Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #12**

2016-02-29 12:27

MOT test number

235863005842

Result**✓ Passed****MOT #11**

2016-02-29 12:00

MOT test number

203951837727

Result**✗ Failed****Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)

**MOT #10**

2015-02-25 11:50

MOT test number

565026555092

Result

✓ Passed

Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #9**

2015-02-24 11:09

MOT test number

366265355003

Result

✗ Failed

Fail Nearside Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)**Fail** Bonnet retaining device ineffective (8.4.2)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Offside Brake pipe excessively corroded (3.6.B.2c)**Fail** Front Tyre has ply or cords exposed (4.1.D.1b)**Notice** Offside front inner drive shaft gaiter split**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8**

2014-03-21 09:12

MOT test number

437490384037

Result

✓ Passed

Notice N/s/f inner cv gaiter small leak**Advice** Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** Front exhaust rubber mount disconnected



MOT #7 2013-03-02 10:14

MOT test number 698621363024

Result ✓ Passed

- Advice** Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Both rear brake disc,s lipped
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #6 2013-02-28 17:21

MOT test number 509639653062

Result ✗ Failed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Both rear brake disc,s lipped
- Fail** Nearside Front coil spring fractured (2.4.C.1a)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #5** 2012-03-13 11:36**MOT test number** 556573672000**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** N/S and O/S rear tyres have slight feathering to the inner edge**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-03-16 16:10**MOT test number** 309515971037**Result** ✓ Passed**MOT #3** 2011-03-12 09:58**MOT test number** 157031971499**Result** ✗ Failed**Fail** Offside Front coil spring fractured (2.4.C.1a)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2010-02-20 10:26**MOT test number** 724221550026**Result** ✓ Passed**MOT #1** 2009-03-11 16:16**MOT test number** 370250379031**Result** ✓ Passed



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 DY06BBX
Plate since	2024-03-28
Current registration	 DY06BBX
Plate since	2024-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-03-18
Last registration	2022-04-16
Complete history	See info



Registration #1	2006-03-18	10 mi
Registration #2	2009-03-11	42.290 mi
Registration #3	2010-02-20	53.624 mi
Registration #4	2011-03-12	68.000 mi
Registration #5	2011-03-16	68.095 mi
Registration #6	2012-03-13	82.250 mi
Registration #7	2013-02-28	97.771 mi
Registration #8	2013-03-02	97.771 mi
Registration #9	2014-03-21	127.391 mi
Registration #10	2015-02-24	136.462 mi
Registration #11	2015-02-25	136.470 mi
Registration #12	2016-03-20	151.337 mi
Registration #13	2016-03-20	151.337 mi
Registration #14	2016-03-20	151.337 mi
Registration #15	2016-03-20	151.337 mi
Registration #16	2016-03-20	151.337 mi
Registration #17	2016-03-20	151.337 mi
Registration #18	2016-03-20	151.337 mi
Registration #19	2016-03-20	151.337 mi
Registration #20	2016-03-20	151.337 mi
Registration #21	2016-03-20	151.337 mi
Registration #22	2016-03-20	151.337 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1753 mm
Height	1413 mm
Length	4288 mm
Wheel base	2614 mm
Kerb weight	1343 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	17090635