



report date: 2024-03-28

General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Blue
Year of manufacture	2012
Top speed	96 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	99 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-07-13
Pictures	12



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-20
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	10
Total items failed	4

MOT #13	2023-12-11 16:16
MOT test number	600825536786
Result	✓ Passed
Next expiry date	2024-12-20
Advice	Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #12	2022-12-14 12:12
MOT test number	714696919259
Result	✓ Passed
Advice	Wipers split at ends
Advice	Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #11	2021-12-15 13:35
MOT test number	931469516048
Result	✓ Passed

MOT #10	2021-12-15 13:35
MOT test number	180064568532
Result	✗ Failed
Pass with rectification	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #9** 2020-12-21 15:55**MOT test number** 810605375942**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing wall (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing wall (5.2.3 (d) (ii))**MOT #8** 2020-12-09 16:14**MOT test number** 726250485289**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing wall (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing wall (5.2.3 (d) (ii))**MAJOR** Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**MOT #7** 2019-06-08 14:10**MOT test number** 744247555890**Result** ✓ Passed**MOT #6** 2019-06-08 14:10**MOT test number** 304247868172**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**MOT #5** 2018-05-24 13:09**MOT test number** 511161247196**Result** ✓ Passed



MOT #4	2017-06-19 12:11
MOT test number	487169248140
Result	✓ Passed
MOT #3	2016-06-20 14:40
MOT test number	382329191248
Result	✓ Passed
Advice	Offside Front tyre wearing on inner edge
Advice	Nearside Front tyre wearing on inner edge
MOT #2	2015-11-05 15:21
MOT test number	552565432634
Result	✓ Passed
MOT #1	2015-06-13 10:23
MOT test number	356994165161
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
20 December 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	20 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2015-05-29
Current registration	*****
Plate since	2015-05-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-06-28
Last registration	2023-12-11
Complete history	See info



Registration #1	2012-06-28	18 mi
Registration #2	2015-06-13	24.798 mi
Registration #3	2015-11-05	28.548 mi
Registration #4	2016-06-20	34.061 mi
Registration #5	2017-06-19	40.336 mi
Registration #6	2018-05-24	41.696 mi
Registration #7	2019-06-08	42.915 mi
Registration #8	2019-06-08	42.915 mi
Registration #9	2019-06-08	42.915 mi
Registration #10	2019-06-08	42.915 mi
Registration #11	2019-06-08	42.915 mi
Registration #12	2019-06-08	42.915 mi
Registration #13	2019-06-08	42.915 mi
Registration #14	2019-06-08	42.915 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	155933