




report date: 2024-03-29

General information

Make	BMW
Model	216 216D SPORT GRAN TOURER
Colour	Grey
Year of manufacture	2016
Top speed	119 mph
0 - 60 mph	11.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.496 cc
Cylinders	3
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	108 g/km
CO2 label	B





## Internet history

### Entry 1

Date	2021-07-10
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://autoonline.co.uk)



MOT history

MOT expiry date	2024-06-26
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	15
Total items failed	1

**MOT #6** 2023-06-27 12:36

**MOT test number** 197350601237

**Result** ✓ Passed

**Next expiry date** 2024-06-26

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))

**MOT #5** 2022-06-13 13:02

**MOT test number** 201159469681

**Result** ✓ Passed

- Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Nail in tyre
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



**MOT #4** 2021-05-14 08:16

**MOT test number** 457479207100

**Result** ✓ Passed

**MOT #3** 2020-08-19 13:41

**MOT test number** 732134920977

**Result** ✓ Passed

**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #2** 2020-08-18 13:33

**MOT test number** 834701153532

**Result** ✗ Failed

**Minor** Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

**Fail** Nearside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #1** 2019-08-28 15:25

**MOT test number** 629542683753

**Result** ✓ Passed

**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 July 2024

✓  
**MOT**

**Expires:**  
26 June 2024

**Tax status** Valid until 1 July

**Days left** 63

**MOT expiry date** 26 June 2024

**Full MOT history** [See MOT history](#)

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	EY66FXW
Plate since	2024-03-29
Current registration	EY66FXW
Plate since	2024-03-29

More info >



**Finance check**

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-09-20
Last registration	2023-06-27
Complete history	<a href="#">See info</a>



Registration #1	2016-09-20	14 mi
Registration #2	2019-08-28	33.140 mi
Registration #3	2020-08-18	40.560 mi
Registration #4	2020-08-19	40.560 mi
Registration #5	2023-06-27	40.560 mi
Registration #6	2023-06-27	40.560 mi
Registration #7	2023-06-27	40.560 mi
Registration #8	2023-06-27	40.560 mi

[More info >](#)



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1800 mm
Height	1612 mm
Length	4556 mm
Wheel base	2780 mm
Kerb weight	1470 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	51 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	32499625