



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK200K AVANTGARDE
Colour	Black
Year of manufacture	2005
Top speed	140 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 4.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.7 mpg
CO2 emission	212 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-07-29
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-04-23
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	30
Total items failed	7

MOT #22	2023-04-24 15:24
MOT test number	973239918764
Result	✓ Passed
Next expiry date	2024-04-23

MOT #21	2023-04-20 13:35
MOT test number	672758659683
Result	✗ Failed
MAJOR Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

MOT #20	2022-07-07 14:35
MOT test number	613935226607
Result	✓ Passed
Advice Exhaust mounting defective (6.1.2 (a))	

**MOT #19** 2022-06-27 11:39**MOT test number** 803065968801**Result** ✗ Failed**Advice** Exhaust mounting defective middle bracket corroded off (6.1.2 (a))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MAJOR** Headlamp aim projected beam image is obviously incorrect o/s and n/s/f headlamp covers blurred diffusing headlamp beam pattern (4.1.2 (c))**MOT #18** 2021-06-14 12:32**MOT test number** 388342510974**Result** ✓ Passed**MOT #17** 2021-06-14 12:32**MOT test number** 683619261880**Result** ✗ Failed**Pass with rectification** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #16** 2020-07-08 09:22**MOT test number** 610748831965**Result** ✓ Passed**MOT #15** 2020-07-08 09:22**MOT test number** 563342611836**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Offside Rear Direction indicator not working (4.4.1 (a) (ii))

**MOT #14** 2019-06-27 09:00**MOT test number** 231699516398**Result** ✓ Passed**MOT #13** 2019-06-27 09:00**MOT test number** 983963477431**Result** ✗ Failed**Pass with rectification** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #12** 2018-06-28 12:24**MOT test number** 343622666255**Result** ✓ Passed**Advice** Nearside Rear tyre wearing on inner edge**MOT #11** 2017-06-28 09:34**MOT test number** 716063829088**Result** ✓ Passed**MOT #10** 2016-07-01 14:10**MOT test number** 999051841545**Result** ✓ Passed**MOT #9** 2015-06-24 16:17**MOT test number** 465265275105**Result** ✓ Passed**Notice** Exhaust hanger broken**Notice** O/s/r tyre slight side wall damage

**MOT #8** 2015-06-23 17:26**MOT test number** 349754275165**Result** ✗ Failed**Notice** N/s mirror glass missing**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Notice** Exhaust hanger broken**Notice** O/s/r tyre slight side wall damage**MOT #7** 2014-10-08 13:19**MOT test number** 845611984246**Result** ✓ Passed**MOT #6** 2014-01-30 15:11**MOT test number** 745400734022**Result** ✓ Passed**MOT #5** 2013-03-27 10:34**MOT test number** 428716083010**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2012-03-28 13:15**MOT test number** 207048982097**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #3** 2011-04-05 17:12**MOT test number** 919215591068**Result** ✓ Passed**Notice** Front and rear undertays fitted preventing full under vehicle inspection**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.2a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.2a)**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.2a)**MOT #2** 2010-04-07 12:02**MOT test number** 962797290081**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.2a)**Advice** Rear rear brake grabbing slightly (3.7.A.5b)**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #1** 2009-04-06 12:37**MOT test number** 962426699072**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 April 2025

✗  
**MOT**  
  
Expired:  
23 April 2024

Tax status	Valid until 1 April
Days left	338
MOT expiry date	23 April 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	YP55XXT
Plate since	2024-03-28
Current registration	YP55XXT
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-11-24
Last registration	2023-04-24
Complete history	<a href="#">See info</a>



Registration #1	2005-11-24	25 mi
Registration #2	2009-04-06	35.238 mi
Registration #3	2010-04-07	38.570 mi
Registration #4	2011-04-05	40.553 mi
Registration #5	2012-03-28	41.809 mi
Registration #6	2013-03-27	42.707 mi
Registration #7	2014-01-30	43.825 mi
Registration #8	2014-10-08	47.420 mi
Registration #9	2015-06-23	51.512 mi
Registration #10	2015-06-24	51.516 mi
Registration #11	2016-07-01	55.844 mi
Registration #12	2017-06-28	57.235 mi
Registration #13	2018-06-28	58.235 mi
Registration #14	2019-06-28	59.235 mi
Registration #15	2020-06-28	60.235 mi
Registration #16	2021-06-28	61.235 mi
Registration #17	2022-06-28	62.235 mi
Registration #18	2023-06-28	63.235 mi
Registration #19	2024-06-28	64.235 mi
Registration #20	2025-06-28	65.235 mi
Registration #21	2026-06-28	66.235 mi
Registration #22	2027-06-28	67.235 mi
Registration #23	2028-06-28	68.235 mi
Registration #24	2029-06-28	69.235 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2690 mm
Kerb weight	1665 kg
Max. allowed weight	2135 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27194030699662