



RENAULT

 **DPI5LWX**


report date: 2024-03-29

General information

Make	RENAULT
Model	KANGOO ML19 DCI
Colour	Grey
Year of manufacture	2015
Top speed	150 mph
0 - 100 km/h	13.3 seconds
0 - 60 mph	16.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	66 kW / 90 HP / 75 BHP
Max. torque	180 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	61.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-07-31
Pictures	38
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-26
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	11
Total items failed	2

MOT #8	2023-09-27 15:51
MOT test number	797219560967
Result	✓ Passed
Next expiry date	2024-09-26

MOT #7	2023-09-27 13:52
MOT test number	177408145384
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre slightly damaged deep cuts on outer side wall (5.2.3 (d) (ii))
Fail	Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #6	2022-09-14 11:41
MOT test number	340091518593
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing also has a nail in it (5.2.3 (d) (ii))

**MOT #5** 2022-09-14 11:41**MOT test number** 865056359928**Result** ✗ Failed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing also has a nail in it (5.2.3 (d) (ii))**MOT #4** 2021-07-20 15:56**MOT test number** 210749975301**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #3** 2020-07-17 08:47**MOT test number** 926252557463**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Centre rear brake light not working**MOT #2** 2019-07-22 08:29**MOT test number** 776594285863**Result** ✓ Passed**MOT #1** 2018-07-26 15:25**MOT test number** 123821612110**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin n/s and o/s worn to minimum (1.1.13 (a) (ii))**Advice** Front Tyre worn close to legal limit/worn on edge n/s and o/s worn to minimum (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
26 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	26 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-07-16
Last registration	2023-09-27
Complete history	See info



Registration #1	2015-07-16	18 mi
Registration #2	2018-07-26	23.862 mi
Registration #3	2019-07-22	27.496 mi
Registration #4	2020-07-17	31.169 mi
Registration #5	2021-07-20	34.202 mi
Registration #6	2022-09-20	35.277 mi
Registration #7	2022-09-20	35.277 mi
Registration #8	2022-09-20	35.277 mi
Registration #9	2022-09-20	35.277 mi
Registration #10	2023-09-27	35.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2138 mm
Height	1805 mm
Length	4282 mm
Wheel base	2 mm
Kerb weight	1205 kg
Max. allowed weight	1884 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2

Number of axles	2
Engine number	D579568