





report date: 2024-03-28

General information

Make	FORD
Model	S-MAX ZETEC TDCI
Colour	Silver
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg



CarCheck.co.uk page 1/10



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-08

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-28

MOT history

MOT #7 2021-02-15 15:58 MOT test number 804035746979

Result ✓ Passed

Next expiry date 2022-03-01

MOT #6 2021-02-15 13:47

MOT test number 666551609976

Result X Failed

Minor Nearside Rear Tyre obviously under inflated (5.2.3 (I))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Towbar with an unsafe modification to primary components bolts (6.1.6 (g) (ii))

Minor Offside Rear Tyre obviously under inflated (5.2.3 (I))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #5 2020-02-12 16:48

MOT test number 506594702316

Result \(\sqrt{Passed} \)

Minor Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

Advice Offside Rear Position lamp has a product on the lens or light source but not adversely affecting light intensity (4.2.3 (b) (ii))

Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #4 2019-02-26 09:39

MOT test number 831317510025

Result

Passed

CarCheck.co.uk page 3/10



report date: 2024-03-28

MOT #3 2019-02-26 09:39

MOT test number 476672653758

Result X Failed

Pass with rectification

Registration plate lamp inoperative in the case of a single lamp or all lamps

(4.7.1 (b) (ii))

MOT #2 2018-03-02 16:33

MOT test number 365577662443

Result

Passed

Advice Offside Rear Tail lamp damaged.

MOT #1 2018-03-02 13:07

MOT test number 917468345193

Result × Failed

Advice Nearside Rear Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)

Advice Offside Rear Tail lamp damaged.

Fail Offside Front Front position lamp(s) not working (1.1.A.3b)

CarCheck.co.uk page 4/10



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-28

\sim		
Owner	hictory	7
OWITCE	HIJLOH	٧

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NE NE
Plate since	
Current registration	NK NY
Plate since	
	More info >

CarCheck.co.uk page 7/10



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2008-12-31
Last registration	2021-02-15
Complete history	See info



Registration #1	2008-12-31	20 mi
Registration #2	2018-03-02	137.066 mi
Registration #3	2018-03-02	137.066 mi
Registration #4	2019-02-26	170.633 mi
Registration #5	2019-02-26	170.633 mi
Registration #6		71.777 66
Registration #7		0.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1897 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 10/10

Number of axles 2

Engine number 8D05019