



report date: 2024-03-28

General information

Make	LAND ROVER
Model	DEFENDER TD XS STATION WAGON
Colour	Grey
Year of manufacture	2010
Top speed	82 mph
0 - 60 mph	15.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel
Consumption city	20.8 mpg
Consumption extra urban	29.1 mpg
Consumption combined	25.5 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-02-26
Pictures	11
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-27
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	35
Total items failed	18

MOT #142024-02-23 10:41

MOT test number382155145730

Result✓ Passed

Next expiry date2025-02-27

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Minor** Offside Rear Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive CHASSIS (5.3.6 (a) (i))
- Advice** Offside Brake pipe corroded, covered in grease or other material TO HOSE (1.1.11 (c))
- Minor** Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Towbar component slightly damaged CROSS MEMBER (6.1.6 (a))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material TO HOSE (1.1.11 (c))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13**

2023-02-27 17:07

MOT test number

771259511882

Result

✓ Passed

Minor

Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Offside Rear Vehicle structure slightly corroded within 30cm of towbar mounting cross member (6.1.6 (i) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Outer Nail in tyre

Minor

Nearside Rear Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Offside Front Brake pipe corroded, covered in grease or other material to hose (1.1.11 (c))

Advice

Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Brake pipe corroded, covered in grease or other material to hose (1.1.11 (c))

**MOT #12**

2023-02-22 10:00

MOT test number

662039585419

Result**✗ Failed**

- Fail** Nearside Rear Reversing lamp inoperative (4.6.1 (a))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material to hose (1.1.11 (c))
- Fail** Offside Front Headlamp aim too high (4.1.2 (a))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Offside Front Drag link end ball joint dust cover insecure so that it no longer prevents the ingress of dirt forward (2.1.3 (g) (ii))
- Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material to hose (1.1.11 (c))
- Fail** Nearside Front Headlamp aim too high (4.1.2 (a))
- Advice** Offside Rear Vehicle structure slightly corroded within 30cm of towbar mounting cross member (6.1.6 (i) (i))
- Advice** Nearside Front Outer Nail in tyre
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Minor** Nearside Rear Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #11

2022-02-14 17:23

MOT test number

741780337653

Result**✓ Passed**

- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #10** 2021-02-26 16:53**MOT test number** 364485048622**Result** ✓ Passed**Advice** Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #9** 2020-02-24 18:00**MOT test number** 555231392155**Result** ✓ Passed**MOT #8** 2019-02-28 09:43**MOT test number** 214416527330**Result** ✓ Passed**MOT #7** 2019-02-25 11:10**MOT test number** 477110579131**Result** ✗ Failed**Fail** Nearside Rear Lower Shock absorbers has an excessively worn bush (5.3.2 (c))**Fail** Stop lamp(s) all not working (4.3.1 (a) (iii))**Fail** Offside Rear Lower Shock absorbers has an excessively worn bush (5.3.2 (c))**MOT #6** 2018-02-12 17:21**MOT test number** 965511494024**Result** ✓ Passed

**MOT #5** 2017-02-27 10:29**MOT test number** 188335290520**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Gearbox oil leak**MOT #4** 2017-02-23 12:10**MOT test number** 215832813018**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Rear Seat belt damaged sufficient to significantly weakened the webbing (5.2.2a)**Fail** Hazard warning lamps inoperative (1.4.B.1b)**Fail** Offside Rear position lamp(s) not working (1.1.A.3b)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Central Front Seat belt retracting mechanism defective (5.2.5b)**Fail** Direction indicators not working all (1.4.A.2c)**Advice** Gearbox oil leak**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #3** 2015-10-13 12:17**MOT test number** 796194123903**Result** ✓ Passed**MOT #2** 2014-10-06 10:09**MOT test number** 926139674285**Result** ✓ Passed**Advice** Offside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)



MOT #1	2013-10-04 16:42
MOT test number	385377073210
Result	✓ Passed
Advice	Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear Lower Shock absorber has a slightly worn bush (2.7.4)
Notice	Front axel ends have a slight weep



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
27 February 2025

Tax status		Valid until 1 May
Days left		367
MOT expiry date		27 February 2025
Full MOT history		See MOT history



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-24
Last registration	2024-02-23
Complete history	See info



Registration #1	2010-09-24	29 mi
Registration #2	2013-10-04	50.549 mi
Registration #3	2014-10-06	56.933 mi
Registration #4	2015-10-13	60.630 mi
Registration #5	2017-02-23	62.139 mi
Registration #6	2017-02-27	62.143 mi
Registration #7	2018-02-12	71.485 mi
Registration #8	2019-02-25	78.163 mi
Registration #9	2020-05-20	85.277 mi
Registration #10	2021-05-20	92.277 mi
Registration #11	2022-05-20	99.277 mi
Registration #12	2023-05-20	106.277 mi
Registration #13	2024-02-23	113.277 mi
Registration #14	2024-02-23	113.277 mi
Registration #15	2024-02-23	113.277 mi
Registration #16	2024-02-23	113.277 mi

More info >



Dimensions & weight

Width	1790 mm
Height	2181 mm
Length	4625 mm
Kerb weight	2111 kg
Max. allowed weight	3050 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	100921212117244DT