





report date: 2024-03-28

General information

Make	FIAT
Model	BRAVO MULTIJET DYNAMIC ECO
Colour	Blue
Year of manufacture	2011
Top speed	116 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	290 Nm at 1.500 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/13



YE110SR

report date: 2024-03-28

Internet history

Entry 1

Date 2022-02-20

Pictures 6

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-03-03
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	27
Total items failed	5

MOT #13		2024-02-26 09:33
MOT test	number	405373297440
Result		✓ Passed
Next expi	y date	2025-03-03
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge edge wear	ing (5.2.3 (e))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both	sides (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge we	aring (5.2.3 (e))
Advice	Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice (a) (ii))		
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/13



MOT #12 2023-03-03 10:33

MOT test number 947678783168

Result Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Oil leak, but not excessive (8.4.1 (a) (i))

Advice Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2022-03-04 10:36

MOT test number 296049286860

Result ✓ Passed

MOT #10 2022-03-02 12:38

MOT test number 835112414933

Result X Failed

MAJOR Suspension arm ball joint excessively worn nsf (5.3.4 (a) (i))

Advice Tyre worn close to legal limit/worn on edge front both (5.2.3 (e))

MAJOR Coil spring fractured or broken osf (5.3.1 (b) (i))

Advice Oil leak, but not excessive osf (8.4.1 (a) (i))

Advice Tyre worn close to legal limit/worn on edge osr (5.2.3 (e))

MOT #9 2021-04-13 13:14

MOT test number 403646964165

Result \rightarrow Passed

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

CarCheck.co.uk page 4/13



Passed

MOT #8 2020-04-17 09:58

MOT test number 733307795910

Result Passed

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #7 2018-05-25 10:38

MOT test number 476724672692

Result

Advice Exhaust system deteriorating

Advice Front Brake disc worn, pitted or scored, but not seriously weakened on inside (1.1.14 (a) (ii))

MOT #6 2017-05-04 14:56

MOT test number 656844983410

Result ✓ Passed

Advice Nearside rear tyre perishing

MOT #5 2017-05-04 10:54

MOT test number 996598692289

Result × Failed

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Nearside rear tyre perishing

Fail Stop lamp remains on when the brakes are released all (1.2.1e)

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 5/13



MOT #4 2016-05-24 09:49

MOT test number 470288044843

Result ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside driveshaft oil seal leaking

MOT #3 2015-05-13 11:43

MOT test number 798713435124

Result ✓ Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2 2014-05-22 11:36

MOT test number 865422544187

Result ✓ Passed

MOT #1 2014-05-22 11:36

MOT test number 238592644498

Result X Failed

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

Pass with rectification Offside Headlamp aim too high (1.8)

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	3 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-


CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



YE110SR

report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report		e?

	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



YE110SR

report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 11/13



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-05-27
Last registration	2024-02-26
Complete history	See info



Registration #1	2011-05-27	26 mi
Registration #2	2014-05-22	38.573 mi
Registration #3	2015-05-13	50.569 mi
Registration #4	2016-05-24	59.742 mi
Registration #5	2017-05-04	63.711 mi
Registration #6	2017-05-04	63.718 mi
Registration #7	2018-05-25	67.420 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		0.00 44
Registration #13		11.777 mi

mn.n.n

More info >

77.777 ms

CarCheck.co.uk page 12/13



Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1320 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	58	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	13/13

Number of axles 2

Engine number 6599982