



report date: 2024-03-28

General information

Make	KIA
Model	CARENS GS
Colour	Black
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	142 BHP
Max. torque	189 Nm at 4.250 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.5 mpg
Consumption extra urban	40.9 mpg
Consumption combined	33.6 mpg
CO2 emission	193 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-08-29
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2024-07-31
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	26
Total items failed	16

MOT #18	2023-07-11 09:23
MOT test number	974544285417
Result	✓ Passed
Next expiry date	2024-07-31

MOT #17	2022-08-01 13:53
MOT test number	701631321981
Result	✓ Passed

MOT #16	2021-09-06 15:56
MOT test number	469441952262
Result	✓ Passed

MOT #15	2020-10-23 13:38
MOT test number	970179408713
Result	✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm bushes (5.3.4 (a) (i))

Advice Condensation in offside front headlight

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm bushes (5.3.4 (a) (i))

**MOT #14**

2020-10-23 13:38

MOT test number

997672316239

Result**✗ Failed**

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm bushes (5.3.4 (a) (i))

Pass with rectification Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm bushes (5.3.4 (a) (i))

Advice Condensation in offside front headlight

Pass with rectification Offside Position lamp not working (4.2.1 (a) (ii))

MOT #13

2019-05-20 13:22

MOT test number

280013009324

Result**✓ Passed**

Advice All under vehicle suspension parts heavily corroded front and back

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Minor Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Front flexible exhaust section slight blow

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear brake backing plate corroded/ deteriorating

**MOT #12**

2018-05-25 12:14

MOT test number

830941681604

Result

✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11

2018-05-22 08:54

MOT test number

454358762538

Result

✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MOT #10

2017-05-05 14:25

MOT test number

121152118767

Result

✓ Passed

MOT #9

2017-05-05 14:04

MOT test number

345193484966

Result

✗ Failed

Fail Nearside front brake binding (3.7.B.1)



MOT #8	2016-05-26 15:53
MOT test number	859865925324
Result	✓ Passed
Advice	Shields fitted

MOT #7	2016-05-26 10:14
MOT test number	488917610125
Result	✗ Failed
Fail	Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
Fail	Nearside Front Front suspension has excessive movement at a tie bar joint (2.5.A.1c)
Advice	Shields fitted
Fail	Offside Front Front suspension has excessive movement at a tie bar joint (2.5.A.1c)
Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)
Fail	Nearside Front Front suspension has excessive play in an outer ball joint lower arm (2.5.B.2a)
Fail	Offside Rear Front suspension has excessive movement at a tie bar joint (2.5.A.1c)

MOT #6	2015-06-10 16:57
MOT test number	268701565493
Result	✓ Passed

MOT #5	2015-06-10 11:11
MOT test number	357561765151
Result	✗ Failed
Fail	Nearside Front coil spring broken (2.4.C.1a)

**MOT #4** 2014-06-19 09:11**MOT test number** 789340074181**Result** ✓ Passed**Notice** Rear discs worn**Notice** Front discs worn**MOT #3** 2013-06-20 13:02**MOT test number** 557351573168**Result** ✓ Passed**MOT #2** 2013-06-20 09:08**MOT test number** 326301873160**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Front discs worn**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Front coil spring cracked (2.4.C.1a)**MOT #1** 2012-06-14 09:52**MOT test number** 916126962198**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
31 July 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	31 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-




Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-06-26
Last registration	2023-07-11
Complete history	See info



Registration #1	2009-06-26	8 mi
Registration #2	2012-06-14	24.581 mi
Registration #3	2013-06-20	30.159 mi
Registration #4	2013-06-20	30.159 mi
Registration #5	2014-06-19	35.389 mi
Registration #6	2015-06-10	41.353 mi
Registration #7	2015-06-10	41.355 mi
Registration #8	2016-05-26	47.316 mi
Registration #9	2016-05-26	47.316 mi
Registration #10	2017-05-05	51.808 mi
Registration #11	2018-05-05	55.317 mi
Registration #12	2018-05-05	55.317 mi
Registration #13	2018-05-05	55.317 mi
Registration #14	2018-05-05	55.317 mi
Registration #15	2018-05-05	55.317 mi
Registration #16	2018-05-05	55.317 mi
Registration #17	2018-05-05	55.317 mi
Registration #18	2018-05-05	55.317 mi
Registration #19	2018-05-05	55.317 mi
Registration #20	2018-05-05	55.317 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1720 mm
Length	4545 mm
Wheel base	2700 mm
Kerb weight	1519 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

Number of axles	2
Engine number	G4KA8H337267