



MLI40KZ

report date: 2024-03-28

General information

Make	LEXUS
Model	IS 300H LUXURY
Colour	White
Year of manufacture	2014
Top speed	125 mph
0 - 60 mph	8.4 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	178 BHP
Max. torque	221 Nm at 4.200 rpm
Engine capacity	2.493 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	61.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 3

Date	2021-06-20
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

Entry 2

Date	2021-06-16
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-06-04
Pictures	18
Listing price	View report



source: [yesauto.com](https://www.yesauto.com)



MOT history

MOT expiry date	2024-05-17
MOT pass rate	100 %
MOT passed	8
Failed MOT tests	0
Total advice items	10
Total items failed	0

MOT #8	2024-04-27 09:25
MOT test number	263072184272
Result	✓ Passed
Next expiry date	2025-05-17
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7	2023-04-22 08:51
MOT test number	740998363830
Result	✓ Passed

MOT #6	2022-05-07 10:04
MOT test number	684215723004
Result	✓ Passed

MOT #5	2021-05-18 14:10
MOT test number	436427502393
Result	✓ Passed

MOT #4	2020-07-14 11:02
MOT test number	153411736869
Result	✓ Passed



MOT #3	2019-03-02 09:20
MOT test number	994095699532
Result	✓ Passed

MOT #2	2018-03-17 12:25
MOT test number	128069854353
Result	✓ Passed
Advice	Offside Front Inner Tyre worn close to the legal limit 2mm (4.1.E.1)
Advice	Offside Rear Inner Tyre worn close to the legal limit 2mm (4.1.E.1)
Advice	Nearside Front Inner Tyre worn close to the legal limit 2mm (4.1.E.1)
Advice	Nearside Rear Inner Tyre worn close to the legal limit 2mm (4.1.E.1)

MOT #1	2017-03-31 14:25
MOT test number	635478522628
Result	✓ Passed
Advice	Nearside Rear tyre inner edge worn
Advice	Offside Front tyre inner edge worn
Advice	Offside Rear tyre inner edge worn
Advice	Nearside Front tyre inner edge worn



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
17 May 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	17 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	B
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-



Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra LEXUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LEXUS? How many owners did this LEXUS have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this LEXUS had different number plates.

Number of plates	1
Current registration	ML14OKZ
Plate since	2024-03-28
Current registration	ML14OKZ
Plate since	2024-03-28

More info >



Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LEXUS is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-03-31
Last registration	2024-04-27
Complete history	See info



Registration #1	2014-03-31	24 mi
Registration #2	2017-03-31	24.258 mi
Registration #3	2018-03-17	30.153 mi
Registration #4	2019-03-02	34.690 mi
Registration #5	2020-07-14	38.403 mi
Registration #6	2021-05-18	50.131 mi
Registration #7	2022-05-20	55.277 mi
Registration #8	2023-05-20	55.277 mi
Registration #9	2023-05-20	55.277 mi
Registration #10	2023-05-20	55.277 mi
Registration #11	2023-05-20	55.277 mi
Registration #12	2024-04-27	55.277 mi

More info >



Car features

The LEXUS factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete LEXUS factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	85%
Pedestrian	80%
Safety systems	66%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1430 mm
Length	4665 mm
Wheel base	2800 mm
Kerb weight	1720 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	2AR1005509