




report date: 2024-03-28

General information

Make	FORD
Model	MONDEO ZETEC BUSINESS EDITION TDCI
Colour	Silver
Year of manufacture	2014
Top speed	118 mph
0 - 100 km/h	11.2 seconds
0 - 60 mph	11.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	85 kW / 116 HP / 113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	109 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-10-11
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-17
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	24
Total items failed	15

MOT #14	2023-12-12 13:46
MOT test number	387076251168
Result	✓ Passed
Next expiry date	2024-12-17
Advice	Offside Front Seat belt slightly damaged (7.1.2 (b) (i))
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Play in steering rack inner joint(s)
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #13	2023-12-11 17:25
MOT test number	700658983396
Result	✗ Failed
Fail	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Offside Front Play in steering rack inner joint(s)
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Offside Front Seat belt slightly damaged (7.1.2 (b) (i))
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #12** 2022-12-06 16:15**MOT test number** 996741043683**Result** ✓ Passed**Advice** Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**Advice** Undertrays fitted**MOT #11** 2021-12-18 08:06**MOT test number** 863479272200**Result** ✓ Passed**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Front Registration plate deteriorated but not likely to be misread NUMBER PLATE CRACKED. (0.1 (b))**MOT #10** 2021-12-14 16:54**MOT test number** 194820919850**Result** ✗ Failed**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Front Registration plate deteriorated but not likely to be misread NUMBER PLATE CRACKED. (0.1 (b))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #9** 2021-02-17 09:10**MOT test number** 112203192546**Result** ✓ Passed**Advice** Nearside Front bumper and wing damaged

**MOT #8** 2021-02-12 11:54**MOT test number** 725900133912**Result** ✗ Failed**Fail** Nearside Front Headlamp aim too low (4.1.2 (a))**Advice** Nearside Front bumper and wing damaged**Fail** Offside Front Side repeater lens defective such that the emitted light is adversely affected (4.4.1 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge badly on edges (5.2.3 (e))**Advice** Nearside Rear Nail in tyre**Fail** Nearside Front Headlamp insecure damaged (4.1.1 (c))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords cuts to sidewall (5.2.3 (d) (i))**Fail** Offside Front Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge badly on edges (5.2.3 (e))**MOT #7** 2020-02-11 16:43**MOT test number** 637755418039**Result** ✓ Passed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #6** 2020-02-11 09:50**MOT test number** 984661638908**Result** ✗ Failed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #5** 2019-02-21 16:23**MOT test number** 908458984586**Result** ✓ Passed**MOT #4** 2019-02-21 11:33**MOT test number** 540109976324**Result** ✗ Failed**Advice** Nearside Rear tyre out of shape/feathered inner edge**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #3** 2018-03-23 10:04**MOT test number** 330659875112**Result** ✓ Passed**MOT #2** 2017-03-09 14:06**MOT test number** 398794520836**Result** ✓ Passed**MOT #1** 2017-03-08 13:16**MOT test number** 396017339201**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
17 December 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	17 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	BU14VDK
Plate since	2019-03-28
Current registration	BU14VDK
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2014-03-31
Last registration	2023-12-12
Complete history	See info



Registration #1	2014-03-31	6 mi
Registration #2	2017-03-08	59.700 mi
Registration #3	2017-03-09	59.700 mi
Registration #4	2018-03-23	82.909 mi
Registration #5	2019-02-21	122.484 mi
Registration #6	2019-02-21	122.485 mi
Registration #7	2020-02-11	161.101 mi
Registration #8	2020-02-11	161.102 mi
Registration #9	2020-02-11	161.102 mi
Registration #10	2020-02-11	161.102 mi
Registration #11	2020-02-11	161.102 mi
Registration #12	2020-02-11	161.102 mi
Registration #13	2020-02-11	161.102 mi
Registration #14	2020-02-11	161.102 mi
Registration #15	2020-02-11	161.102 mi
Registration #16	2020-02-11	161.102 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2092 mm
Height	1500 mm
Length	4784 mm
Wheel base	2850 mm
Kerb weight	1396 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	EJ26323