




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SPORT
Colour	Grey
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-21
Pictures	23
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-09
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	19
Total items failed	4

MOT #16	2023-06-08 14:31
MOT test number	991435415362
Result	✓ Passed
Next expiry date	2024-06-09

MOT #15	2022-06-10 14:01
MOT test number	932265181913
Result	✓ Passed

MOT #14	2021-06-01 15:14
MOT test number	391839330188
Result	✓ Passed

MOT #13	2020-12-03 12:06
MOT test number	874056530796
Result	✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

MOT #12	2019-12-05 11:53
MOT test number	780977795025
Result	✓ Passed

Advice Nearside Front Lower Vehicle structure is deformed but structural rigidity is not significantly reduced SEAL (6.1.1 (a) (i))

**MOT #11** 2019-12-04 09:14**MOT test number** 189371981474**Result** ✗ Failed**Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Inner Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Minor** Nearside Front Lower Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Lower Vehicle structure is deformed but structural rigidity is not significantly reduced SEAL (6.1.1 (a) (i))**Advice** Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #10** 2018-12-05 10:44**MOT test number** 541805199886**Result** ✓ Passed**Advice** Front Play in steering rack inner joint(s) both side**MOT #9** 2017-12-08 09:15**MOT test number** 312433601249**Result** ✓ Passed**Advice** Nearside Rear Rear reflector slightly damaged but function not impaired (1.5.1c)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2016-12-09 10:31**MOT test number** 592778756899**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)**Advice** Engine cover insecure

**MOT #7** 2016-12-07 12:51**MOT test number** 160432192703**Result** ✗ Failed**Fail** Central Rear Stop lamp not working (1.2.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)**Fail** Offside Front Front suspension has excessive movement at a wishbone pin or bush front bush (2.5.A.1c)**Advice** Engine cover insecure**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)**MOT #6** 2015-12-09 16:52**MOT test number** 955082891159**Result** ✓ Passed**MOT #5** 2015-01-08 16:30**MOT test number** 338478605015**Result** ✓ Passed**MOT #4** 2014-01-09 12:12**MOT test number** 256179204097**Result** ✓ Passed**MOT #3** 2014-01-08 17:47**MOT test number** 435478004058**Result** ✗ Failed**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



MOT #2	2013-01-22 17:32
MOT test number	755032523004
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components

MOT #1	2012-01-05 16:58
MOT test number	808395802018
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
9 June 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	9 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-04-18
Last registration	2023-06-08
Complete history	See info



Registration #1	2008-04-18	15 mi
Registration #2	2012-01-05	20.152 mi
Registration #3	2013-01-22	26.562 mi
Registration #4	2014-01-08	32.379 mi
Registration #5	2014-01-09	32.379 mi
Registration #6	2015-01-08	139.094 mi
Registration #7	2015-12-09	45.397 mi
Registration #8	2016-12-07	53.525 mi
Registration #9	2016-12-09	53.526 mi
Registration #10	2016-12-09	53.526 mi
Registration #11	2016-12-09	53.526 mi
Registration #12	2016-12-09	53.526 mi
Registration #13	2016-12-09	53.526 mi
Registration #14	2016-12-09	53.526 mi
Registration #15	2016-12-09	53.526 mi
Registration #16	2016-12-09	53.526 mi
Registration #17	2016-12-09	53.526 mi
Registration #18	2016-12-09	53.526 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1738 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BKP 282994