





report date: 2024-03-29

General information

Make	PEUGEOT
Model	107 URBAN LITE
Colour	Silver
Year of manufacture	2011
Top speed	98 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	103 g/km
CO2 label	В



CarCheck.co.uk page 1/13



B 4	\sim $-$			
10.71	α	- h	sto	rv
101	() I		510	II V
	•		-	. ,

MOT expiry date	2025-04-22
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	38
Total items failed	5

MOT #14		2024-04-02 09:59
MOT test	number	717955073877
Result		✓ Passed
Next expi	ry date	2025-04-22
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened	d (1.1.14 (a) (ii))
Advice	Central Brake pipe corroded, covered in grease or other material From from	nt to O/S/R (1.1.11 (c))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weaken	ed (1.1.14 (a) (ii))
Advice	Central Brake pipe corroded, covered in grease or other material From from	nt to N/S/R (1.1.11 (c))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1	.11 (c))

CarCheck.co.uk page 2/13



MOT #13 2023-04-21 14:26

MOT test number 169056897627

Result ✓ Passed

Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Central Brake pipe corroded, covered in grease or other material Front to O/S/R (1.1.11 (c))

Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Central Brake pipe corroded, covered in grease or other material Front to N/S/R (1.1.11 (c))

MOT #12 2022-04-22 15:23

MOT test number 777694477864

Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #11 2021-04-23 15:20

MOT test number 161900582648

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 3/13



MOT #10 2021-04-23 15:20

MOT test number 157597517751

Result X Failed

Pass with rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #9 2020-02-29 12:49

MOT test number 566923270178

Result
✓ Passed

Advice Brake pipe corroded, covered in grease or other material front to n/s/r (1.1.11 (c))

MOT #8 2020-02-28 18:12

MOT test number 259766279009

Result × Failed

Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Brake pipe corroded, covered in grease or other material front to n/s/r (1.1.11 (c))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7 2019-09-16 15:37

MOT test number 783881825781

Result \(\sqrt{Passed} \)

Minor Nearside Obligatory mirror slightly loose (3.3 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Non obligatory mirror damaged

CarCheck.co.uk page 4/13



MOT #6 2018-09-10 10:11

MOT test number 215477245812

Advice Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MOT #5 2017-09-19 08:58

MOT test number 892703311268

Result

Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened x2 (3.5.1i)

MOT #4 2016-06-29 11:46

MOT test number 569365072320

Result \(\sqrt{Passed} \)

Advice Door mirror insecure at n/s

Advice Surface rust on front brake disc o/s & n/s

Advice Rear tyre wearing on inner edge at o/s

MOT #3 2015-01-16 16:04

MOT test number 846146315095

Result

Passed

Notice Items removed from driver's view prior to test

CarCheck.co.uk page 5/13



MOT #2 2015-01-16 10:52

MOT test number 485356215030

Result X Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Notice Nail in o/s rear tyre.

Notice Items removed from driver's view prior to test

Fail Offside Headlamp aim too high (1.8)

Fail Centre Windscreen wiper does not clear the windscreen effectively (8.2.2)

Notice Repair to n/s door mirror.

MOT #1 2014-01-15 09:50

MOT test number 568735714071

Result \(\sqrt{Passed} \)

Notice Front tyre at n/s wearing on outer edge.

Notice Rear tyre at o/s wearing on outer edge.

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	22 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-01-28
Last registration	2024-04-02
Complete history	See info



Registration #1	2011-01-28	14 mi
Registration #2	2014-01-15	20.823 mi
Registration #3	2015-01-16	39.099 mi
Registration #4	2015-01-16	39.099 mi
Registration #5	2016-06-29	48.379 mi
Registration #6	2017-09-19	48.682 mi
Registration #7	2018-09-10	53.274 mi
Registration #8	2019-09-16	71.314 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		D.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
50295	
50482	
50501	
60566	
60567	
50569	

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	7010031

CarCheck.co.uk page 13/13