





report date: 2024-03-29

General information

Make	CITROEN
Model	NEMO 8V
Colour	Blue
Year of manufacture	2010
Top speed	96 mph
0 - 60 mph	16.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	73 BHP
Max. torque	118 Nm at 2.600 rpm
Engine capacity	1.360 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	155 g/km
CO2 label	G



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-10-12

Pictures 18

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-01-18
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	15
Total items failed	1

MOT #15	2024-01-16 10:20
MOT test number	163613400914
Result	✓ Passed
Next expiry date	2025-01-18
Advice Nearside Rear Nail in tyre	

MOT #14	2023-01-11 12:37
MOT test number	115317704906
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #13	2022-01-08 10:27
MOT test number	841923157127
Result	✓ Passed

MOT #12	2022-01-08 10:27
MOT test number	965070026773
Result	▼ Failed
Pass with rectification	Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #11

MOT test number

520415426645

Result

Advice Front pads wearing low

MOT #10

MOT test number

268967997326

Result

Advice Front pads wearing low

MAJOR Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #9

MOT test number

644031422626

Result

✓ Passed

MOT test number

Result

Advice
Oil leak, but not excessive (8.4.1 (a) (i))

Advice
Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice
Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-29

2019-03-13 15:18 **MOT #7** 846824573579 **MOT** test number Result × Failed **MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

 MOT #6
 2018-03-22 13:04

 MOT test number
 863672229393

 Result
 ✓ Passed

MOT #5

MOT test number

134681855230

Result

✓ Passed

MOT #4

MOT test number

Result

Advice Front wipers noisey across screen when operated

Advice Engine has oil leak

MOT #3 2015-03-17 12:56

MOT test number 117776975455

Result ✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

 MOT #2
 2014-04-01 13:37

 MOT test number
 858941094048

 Result
 ✓ Passed

 MOT #1
 2013-04-04 13:29

 MOT test number
 879494693081

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	18 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



factor scincore

HY10KWC

report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this CITROEN had different number plates.

CarCheck.co.uk page 10/13



Finance check

settled.

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-04-23
Last registration	2024-01-16
Complete history	See info



Registration #1	2010-04-23	10 mi
Registration #2	2013-04-04	6.448 mi
Registration #3	2014-04-01	9.866 mi
Registration #4	2015-03-17	12.574 mi
Registration #5	2016-03-23	15.051 mi
Registration #6	2017-03-10	16.427 mi
Registration #7	2018-03-22	17.725 mi
Registration #8	2019-03-13	18.360 mi
Registration #9	2019-03-13	18.357 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		10.707 au

 $\quad \text{More info} \ \ >$

CarCheck.co.uk page 12/13



Safety ratings

NCAP rating	***
Adult	59%
Children	74%
Pedestrian	55%
Safety systems	29%
Overall rating	58%
Video	see crash video



Dimensions & weight

Width	1816 mm
Height	1721 mm
Length	3959 mm
Wheel base	2513 mm
Kerb weight	1165 kg
Max. allowed weight	1690 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FSW76102207

CarCheck.co.uk page 13/13