





report date: 2024-03-28

General information

Make	LAND ROVER
Model	RANGE ROVER SPORT SDV6 HSE
Colour	Grey
Year of manufacture	2016
Top speed	130 mph
0 - 100 km/h	7.2 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	225 kW / 306 HP / 306 BHP
Max. torque	700 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	44.1 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I



CarCheck.co.uk page 1/11



Internet history


Entry 1

Date 2021-10-15

Pictures 23

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-11-03
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	14
Total items failed	1

MOT #6		2023-10-31 16:43
MOT test	number	933333615727
Result		✓ Passed
Next expi	y date	2024-11-03
Advice Offside Rear Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))		
Advice	Nearside Rear Outer Brake pipe corroded, covered in grease or other m	naterial (1.1.11 (c))

MOT #5	2022-11-04 13:44
MOT test number	628862001162
Result	✓ Passed

Result		✓ Passed
MOT #4		2021-11-04 16:10
MOT test	number	642597612653
Result		✓ Passed
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/11



MOT #3 2021-10-29 12:13

MOT test number 595153745934

Result × Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #2 2020-10-26 16:26

MOT test number 804681216871

Result ✓ Passed

MOT #1 2019-10-16 13:21

MOT test number 217408665708

Result \rightarrow Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	3 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.


Damage 1

Date	
Category	
Туре	

Damage 2

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many of ROVER have? Check it in the premium report and see all owner registrations. Download to	

	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	NK NE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-10-26
Last registration	2023-10-31
Complete history	See info



Registration #1	2016-10-26	19 mi
Registration #2	2019-10-16	19.451 mi
Registration #3	2020-10-26	24.767 mi
Registration #4		11.777 es
Registration #5		91.777 esi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es

More info >

page 10/11 CarCheck.co.uk



Safety ratings

NCAP rating	****
Adult	91%
Children	84%
Pedestrian	63%
Safety systems	86%
Overall rating	84%
Video	see crash video



Dimensions & weight

Width	2220 mm
Height	1801 mm
Length	4856 mm
Wheel base	2923 mm
Kerb weight	2115 kg
Max. allowed weight	3050 kg

Additional information

Fuel tank capacity	89 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1089355306DT

CarCheck.co.uk page 11/11