



report date: 2024-03-29

General information

Make	KIA
Model	CARENS 3 ECODYNAMICS CRDI
Colour	Black
Year of manufacture	2013
Top speed	119 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	330 Nm at 2.000 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	61.4 mpg
Consumption combined	56.5 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-10-06
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-07
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	43
Total items failed	0

MOT #11	2023-12-02 10:50
MOT test number	397398536966
Result	✓ Passed
Next expiry date	2024-12-07
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10**

2022-12-03 13:23

MOT test number

552464459561

Result

✓ Passed

- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread Cracked (0.1 (b))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Exhaust mounting defective (6.1.2 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Lipped (1.1.14 (a) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Lipped (1.1.14 (a) (ii))

**MOT #9** 2022-12-03 11:24**MOT test number** 102635659474**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Lipped (1.1.14 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread Cracked (0.1 (b))**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Exhaust mounting defective (6.1.2 (a))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Lipped (1.1.14 (a) (ii))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**DANGEROUS** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #8** 2021-12-08 12:05**MOT test number** 141272829400**Result** ✓ Passed**MOT #7** 2021-07-13 10:43**MOT test number** 620697631563**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Items removed from driver's view prior to test phone holder**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #6** 2020-07-03 14:22**MOT test number** 933625489951**Result** ✓ Passed**Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords edge (5.2.3 (d) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #5** 2019-06-24 11:29**MOT test number** 643056126014**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Items removed from driver's view prior to test**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #4** 2018-07-06 13:05**MOT test number** 500183501290**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge heavily worn inner edge (5.2.3 (e))**MOT #3** 2018-07-06 10:59**MOT test number** 535812780052**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge heavily worn inner edge (5.2.3 (e))**MAJOR** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))



MOT #2	2017-07-12 09:55
MOT test number	600387897655
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside rear and offside front tyres- wearing edges

MOT #1	2016-07-08 12:04
MOT test number	660829083031
Result	✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
7 December 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	7 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	GV13KZB
Plate since	2024-03-29
Current registration	GV13KZB
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-07-13
Last registration	2023-12-02
Complete history	See info



Registration #1	2013-07-13	9 mi
Registration #2	2016-07-08	22.334 mi
Registration #3	2017-07-12	27.719 mi
Registration #4	2018-07-06	31.949 mi
Registration #5	2018-07-06	31.950 mi
Registration #6	2019-06-24	35.246 mi
Registration #7	2020-07-03	38.241 mi
Registration #8	2020-06-29	38.241 mi
Registration #9	2020-06-29	38.241 mi
Registration #10	2020-06-29	38.241 mi
Registration #11	2020-06-29	38.241 mi
Registration #12	2020-06-29	38.241 mi
Registration #13	2023-12-02	38.241 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1805 mm
Height	1605 mm
Length	4525 mm
Wheel base	2750 mm
Kerb weight	1716 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	D4FDDH508041