




report date: 2024-03-29

General information

Make	FORD
Model	FOCUS C-MAX ZETEC CLI. D
Colour	Silver
Year of manufacture	2006
Top speed	117 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	242 Nm at 2.000 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	70.6 mpg
Consumption combined	58.9 mpg
CO2 emission	127 g/km
CO2 label	D





## Internet history

### Entry 1

Date	2021-09-03
Pictures	36
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)



MOT history

MOT expiry date	2024-09-25
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	22
Total items failed	3

MOT #17 2023-09-26 13:02

MOT test number 177647610694

Result ✓ Passed

Next expiry date 2024-09-25

**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16 2022-09-22 15:52

MOT test number 173703097001

Result ✓ Passed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice** Child Seat fitted not allowing full inspection of adult belt

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))



<b>MOT #15</b>	2022-09-22 12:57
<b>MOT test number</b>	335690063478
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Fail</b>	Offside Front Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
<b>Advice</b>	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
<b>Advice</b>	Child Seat fitted not allowing full inspection of adult belt
<b>Minor</b>	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Fail</b>	Nearside Front Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

<b>MOT #14</b>	2021-10-01 15:09
<b>MOT test number</b>	805753054072
<b>Result</b>	✓ Passed

<b>MOT #13</b>	2020-10-14 09:12
<b>MOT test number</b>	606562826034
<b>Result</b>	✓ Passed

<b>MOT #12</b>	2019-10-15 10:25
<b>MOT test number</b>	889806185386
<b>Result</b>	✓ Passed
<b>Minor</b>	Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge INNER EDGE. (5.2.3 (e))



<b>MOT #11</b>	2018-10-17 10:57
<b>MOT test number</b>	306770754973
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Nail in tyre

<b>MOT #10</b>	2017-10-11 10:36
<b>MOT test number</b>	808916808318
<b>Result</b>	✓ Passed

<b>MOT #9</b>	2017-10-11 10:36
<b>MOT test number</b>	726805640084
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

<b>MOT #8</b>	2016-10-19 08:37
<b>MOT test number</b>	932688499624
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	VEHICLE UNDER COVER FITTED.

<b>MOT #7</b>	2015-10-14 11:40
<b>MOT test number</b>	319373722164
<b>Result</b>	✓ Passed

<b>MOT #6</b>	2014-10-14 11:26
<b>MOT test number</b>	588957284211
<b>Result</b>	✓ Passed



<b>MOT #5</b>	2013-10-10 09:39
<b>MOT test number</b>	407893483200
<b>Result</b>	✓ Passed
<b>MOT #4</b>	2012-10-10 10:22
<b>MOT test number</b>	397124982412
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2011-10-10 15:13
<b>MOT test number</b>	477713381243
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2010-10-11 11:06
<b>MOT test number</b>	240054780215
<b>Result</b>	✓ Passed
<b>MOT #1</b>	2009-10-19 12:20
<b>MOT test number</b>	871552599289
<b>Result</b>	✓ Passed



## Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 October 2024

✓  
**MOT**

**Expires:**  
25 September 2024

**Tax status** Valid until 1 October

**Days left** 154

**MOT expiry date** 25 September 2024

**Full MOT history** [See MOT history](#)

## Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-




**Damage history**

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.


**Damage 1**

<b>Date</b>	
<b>Category</b>	
<b>Type</b>	



**Damage 2**

<b>Date</b>	
<b>Category</b>	
<b>Type</b>	



**Extra FORD salvage check**



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

**More info >**



**Vehicle valuation**

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EA56GHK
Plate since	2024-03-29
Current registration	EA56GHK
Plate since	2024-03-29

More info >



**Finance check**

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-10-31
Last registration	2023-09-26
Complete history	<a href="#">See info</a>



Registration #1	2006-10-31	18 mi
Registration #2	2009-10-19	40.383 mi
Registration #3	2010-10-11	46.934 mi
Registration #4	2011-10-10	51.491 mi
Registration #5	2012-10-10	55.982 mi
Registration #6	2013-10-10	60.947 mi
Registration #7	2014-10-14	63.934 mi
Registration #8	2015-10-14	66.251 mi
Registration #9	2016-10-19	68.626 mi
Registration #10	2017-10-11	71.831 mi
Registration #11	2018-10-11	75.277 mi
Registration #12	2019-10-11	78.723 mi
Registration #13	2020-10-11	82.169 mi
Registration #14	2021-10-11	85.615 mi
Registration #15	2022-10-11	89.061 mi
Registration #16	2023-09-26	92.507 mi
Registration #17	2023-09-26	92.507 mi
Registration #18	2023-09-26	92.507 mi
Registration #19	2023-09-26	92.507 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1840 mm
Height	1497 mm
Length	4342 mm
Wheel base	2640 mm
Kerb weight	1370 kg
Max. allowed weight	1795 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	6U84977