



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA VVT EXCLUSIV
Colour	Silver
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-11-04
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-30
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	18
Total items failed	9

MOT #16	2023-10-31 13:50
MOT test number	848455752363
Result	✓ Passed
Next expiry date	2024-10-30
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Oil leak, but not excessive Engine (8.4.1 (a) (i))

MOT #15	2023-10-30 17:35
MOT test number	247890019507
Result	✗ Failed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Offside Rear Position lamp not working (4.2.1 (a) (ii))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Oil leak, but not excessive Engine (8.4.1 (a) (i))
Fail	Rear fog lamp not working (4.5.1 (a) (ii))
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #14** 2022-10-13 17:03**MOT test number** 576415462725**Result** ✓ Passed**Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))**MOT #13** 2022-10-13 10:03**MOT test number** 902439691717**Result** ✗ Failed**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))**MOT #12** 2021-10-20 10:51**MOT test number** 518664421339**Result** ✓ Passed**MOT #11** 2020-09-01 13:36**MOT test number** 739105293625**Result** ✓ Passed**Advice** Slight knock on the steering system**Advice** N/s dip pattern weak**Advice** Oil leaks on engine and onto exhaust system**MOT #10** 2019-08-22 12:25**MOT test number** 913635800542**Result** ✓ Passed

**MOT #9** 2018-08-24 09:55**MOT test number** 318766049576**Result** ✓ Passed**MOT #8** 2018-08-23 13:14**MOT test number** 635321465180**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Rear Registration plate inscription illegible (0.1 (b))**Fail** Front Headlamp aim too low (4.1.2 (a))**MOT #7** 2017-08-09 15:04**MOT test number** 323074484717**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nail in o/s/f tyre**MOT #6** 2016-08-12 12:32**MOT test number** 717232708982**Result** ✓ Passed**MOT #5** 2015-09-04 12:49**MOT test number** 196791748181**Result** ✓ Passed

**MOT #4** 2014-03-04 15:22**MOT test number** 289563964053**Result** ✓ Passed**Advice** Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Rear shocks weak**Advice** Front Tie bar/rod has slight play in a ball joint (2.4.G.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2012-12-08 12:18**MOT test number** 158893542380**Result** ✓ Passed**Advice** Rear Shock absorber has a slightly reduced damping effect (2.7.5)**MOT #2** 2011-12-06 11:40**MOT test number** 547270741302**Result** ✓ Passed**MOT #1** 2011-12-06 09:38**MOT test number** 936700141366**Result** ✗ Failed**Fail** Offside Rear Body has a sharp edge caused by damage (6.1.C.1)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
30 October 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	30 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	LV58WKK
Plate since	2019-09-29
Current registration	LV58WKK
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-12-12
Last registration	2023-10-31
Complete history	See info



Registration #1	2008-12-12	10 mi
Registration #2	2011-12-06	17.774 mi
Registration #3	2011-12-06	17.774 mi
Registration #4	2012-12-08	24.601 mi
Registration #5	2014-03-04	33.113 mi
Registration #6	2015-09-04	38.590 mi
Registration #7	2016-08-12	44.838 mi
Registration #8	2017-08-09	49.175 mi
Registration #9	2018-08-23	52.231 mi
Registration #10	2019-08-23	55.287 mi
Registration #11	2020-08-23	58.343 mi
Registration #12	2021-08-23	61.399 mi
Registration #13	2022-08-23	64.455 mi
Registration #14	2023-08-23	67.511 mi
Registration #15	2024-08-23	70.567 mi
Registration #16	2025-08-23	73.623 mi
Registration #17	2026-08-23	76.679 mi
Registration #18	2027-08-23	79.735 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20KV4564