



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SPORT 5 STR
Colour	Black
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg



LABEL UNKNOWN

**MOT history**

MOT #20	2022-02-08 11:20
MOT test number	107062962933
Result	✓ Passed
Next expiry date	2023-02-07
Advice	Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #19	2021-02-02 14:57
MOT test number	488241461804
Result	✓ Passed
Advice	Underbody tray fitted
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive both sides (5.3.6 (a) (i))
Advice	Rear Service brake binding but not excessively both sides (1.2.1 (f))
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #18	2020-01-15 11:38
MOT test number	880150165611
Result	✗ Failed

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Central Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Fail Tailgate cannot be secured in the closed position (6.2.1 (e))

**MOT #17** 2019-02-04 11:49**MOT test number** 726753181936**Result** ✓ Passed**MOT #16** 2018-02-09 10:49**MOT test number** 662588588327**Result** ✓ Passed

Advice Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Advice Front Suspension arm rubber bush deteriorated but not resulting in excessive movement o/s and n/s (2.4.G.2)

MOT #15 2017-01-27 15:55**MOT test number** 122912470747**Result** ✓ Passed**MOT #14** 2016-01-28 11:55**MOT test number** 383167064611**Result** ✓ Passed**MOT #13** 2015-03-19 16:21**MOT test number** 469978475069**Result** ✓ Passed

Notice Engine management light on.

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice Nail in offside rear tyre

**MOT #12**

2015-03-19 12:49

MOT test number

995188175049

Result**✗ Failed****Notice** Engine management light on.**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Notice** Nail in offside rear tyre**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #11**

2014-03-20 15:22

MOT test number

336239174084

Result**✓ Passed****Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #10**

2014-03-20 15:22

MOT test number

919259874088

Result**✗ Failed**

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Pass with rectification Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Pass with rectification Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

MOT #9

2013-03-22 10:10

MOT test number

187321583079

Result**✓ Passed**

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Notice Offside rear tyre worn smooth.

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice Engine management light on.

**MOT #8**

2013-03-22 10:10

MOT test number

366481783088

Result**✗ Failed**

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Offside rear tyre worn smooth.

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Pass with rectification Offside Stop lamp not working (1.2.1b)

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

Notice Engine management light on.

MOT #7

2012-03-22 16:56

MOT test number

959872582094

Result**✓ Passed**

Advice Offside Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice Child seat fitted not allowing full inspection of adult belt

Advice Nearside Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6**

2012-03-22 14:50

MOT test number

687402682098

Result**✗ Failed**

Fail Nearside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Notice Child seat fitted not allowing full inspection of adult belt

Advice Offside Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Advice Nearside Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5

2011-03-11 15:50

MOT test number

148490171425

Result**✓ Passed****MOT #4**

2011-03-11 10:12

MOT test number

539250671077

Result**✗ Failed**

Fail Offside Rear coil spring fractured (2.4.C.1a)

MOT #3

2010-03-17 16:47

MOT test number

434936070055

Result**✓ Passed**

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2009-03-13 14:57
MOT test number	794022679000
Result	✓ Passed
MOT #1	2008-03-05 15:11
MOT test number	301525568041
Result	✓ Passed



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KY05BXO
Plate since	2024-03-29
Current registration	 KY05BXO
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-03-15
Last registration	2022-02-08
Complete history	See info



Registration #1	2005-03-15	20 mi
Registration #2	2008-03-05	26.271 mi
Registration #3	2009-03-13	34.508 mi
Registration #4	2010-03-17	40.778 mi
Registration #5	2011-03-11	45.423 mi
Registration #6	2011-03-11	45.423 mi
Registration #7	2012-03-22	51.815 mi
Registration #8	2012-03-22	51.815 mi
Registration #9	2013-03-22	57.460 mi
Registration #10	2014-03-20	63.338 mi
Registration #11	2015-03-20	63.338 mi
Registration #12	2016-03-20	63.338 mi
Registration #13	2017-03-20	63.338 mi
Registration #14	2018-03-20	63.338 mi
Registration #15	2019-03-20	63.338 mi
Registration #16	2020-03-20	63.338 mi
Registration #17	2021-03-20	63.338 mi
Registration #18	2022-03-20	63.338 mi
Registration #19	2023-03-20	63.338 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1561 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BKD 273117