



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	LAND CRUISER D-4D LC4 8 SEATS
Colour	Black
Year of manufacture	2003
Top speed	106 mph
0 - 60 mph	12.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	343 Nm at 1.600 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	21.6 mpg
Consumption extra urban	32.5 mpg
Consumption combined	27.2 mpg
CO2 emission	277 g/km
CO2 label	M






Internet history

Entry 1

Date	2021-12-23
Pictures	14
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-02-08
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	38
Total items failed	8

MOT #20	2022-02-09 14:52
MOT test number	917074020778
Result	✓ Passed
Next expiry date	2023-02-08

MOT #19	2022-01-28 13:24
MOT test number	197901175536
Result	✗ Failed
MAJOR Offside Headlamp light source and lamp not compatible (4.1.4 (c))	
DANGEROUS Offside Steering rack insecure to the extent there is excessive movement at the mountings (2.1.3 (a) (ii))	
MAJOR Nearside Headlamp light source and lamp not compatible (4.1.4 (c))	
DANGEROUS Nearside Steering rack insecure to the extent there is excessive movement at the mountings (2.1.3 (a) (ii))	
MAJOR Offside Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #18	2020-12-19 12:13
MOT test number	471937195918
Result	✓ Passed
Advice Service brake efficiency only just met.it would appear that the braking system requires adjustment or repair.	
Advice Rear Shock absorbers light misting of oil or has limited damping effect offside nearside (5.3.2 (b))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

**MOT #17** 2019-12-28 12:55**MOT test number** 745784531921**Result** ✓ Passed**Advice** Shock absorbers light misting of oil or has limited damping effect o/s n/s Front and rear (5.3.2 (b))**MOT #16** 2018-12-19 11:22**MOT test number** 779682965421**Result** ✓ Passed**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Suspension component mounting prescribed area is corroded but not considered excessive O/S N/S FRONT AND REAR (5.3.6 (a) (i))**Advice** Nearside Front Anti-roll bar damaged but not seriously weakened (5.3.3 (b) (i))**MOT #15** 2017-12-21 11:18**MOT test number** 430292636470**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Suspension component mounting prescribed area is corroded but not considered excessive front and rear o/s n/s and inner sills (2.4.A.3)**MOT #14** 2016-12-21 10:58**MOT test number** 467805512972**Result** ✓ Passed**Advice** Rear Shock absorber has a light misting of oil o/s n/s (2.7.3)**MOT #13** 2015-12-22 15:21**MOT test number** 186642271249**Result** ✓ Passed

**MOT #12** 2014-12-19 15:11**MOT test number** 475923254407**Result** ✓ Passed**Advice** Rear coil spring corroded (2.4.C.1b)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #11** 2013-12-21 13:47**MOT test number** 779505353370**Result** ✓ Passed**Advice** Rear coil spring corroded (2.4.C.1b)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #10** 2012-12-27 14:03**MOT test number** 116362962343**Result** ✓ Passed**MOT #9** 2012-01-05 13:18**MOT test number** 448865002012**Result** ✓ Passed**Advice** Offside front brake grabbing slightly (3.7.A.2b)**MOT #8** 2011-01-12 10:21**MOT test number** 476922411040**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)

**MOT #7** 2010-01-07 15:40**MOT test number** 160967100055**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2010-01-07 15:40**MOT test number** 894167200090**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2009-01-07 13:10**MOT test number** 274937209056**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2008-01-19 13:17**MOT test number** 723299518020**Result** ✓ Passed

**MOT #3** 2008-01-17 15:15**MOT test number** 402857218061**Result** ✗ Failed

- Fail** Service brake: efficiency below requirements (3.7.C.1a)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Offside Front brake disc excessively scored (3.5.1h)
- Fail** Parking brake: efficiency below requirements (3.7.C.1b)
- Fail** Rear registration plate character(s) incorrectly spaced (6.3.4a)
- Notice** Brakes not tested on decelerometer on road due to worn out front brakes
- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #2 2007-01-06 14:14**MOT test number** 954826407021**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Nearside front tyre worn to limit
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #1 2006-01-09 14:59**MOT test number** 111039706091**Result** ✓ Passed

- Notice** Front and rear inner pads worn very low will need replacing soon



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2003-01-16
Last registration	2022-02-09
Complete history	See info



Registration #1	2003-01-16	28 mi
Registration #2	2006-01-09	37.849 mi
Registration #3	2007-01-06	49.379 mi
Registration #4	2008-01-17	64.065 mi
Registration #5	2008-01-19	64.071 mi
Registration #6	2009-01-07	73.253 mi
Registration #7	2010-01-07	83.195 mi
Registration #8	2011-01-12	92.005 mi
Registration #9	2012-01-05	102.672 mi
Registration #10	2012-12-27	108.679 mi
Registration #11	2013-12-21	115.715 mi
Registration #12	2014-01-01	122.751 mi
Registration #13	2014-01-01	129.787 mi
Registration #14	2014-01-01	136.823 mi
Registration #15	2014-01-01	143.859 mi
Registration #16	2014-01-01	150.895 mi
Registration #17	2014-01-01	157.931 mi
Registration #18	2014-01-01	164.967 mi
Registration #19	2014-01-01	172.003 mi
Registration #20	2014-01-01	179.039 mi
Registration #21	2014-01-01	186.075 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1875 mm
Height	1905 mm
Length	4850 mm
Wheel base	2790 mm
Kerb weight	1990 kg

Additional information

Fuel tank capacity	87 l
Fuel delivery	Direct Injection
Number of doors	5
Engine number	1KD0994435