





report date: 2024-03-28

General information

Make	HYUNDAI
Model	TUCSON GDI SE NAV BLUE DRIVE
Colour	Beige
Year of manufacture	2018
Top speed	113 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	161 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.8 mpg
CO2 emission	147 g/km
CO2 label	F



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-08-24

Pictures 16

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



DP18KZV report date: 2024-03-28

MOT history

MOT expiry date	2024-08-25
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	12
Total items failed	3

MOT #4	2023-08-26 11:01
MOT test number	620333187566
Result	✓ Passed
Next expiry date	2024-08-25
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #3		2022-08-19 15:53
MOT test	number	823183102743
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	i))
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #2 2022-08-19 10:38 **MOT** test number 787262573081 Result **X** Failed **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i)) Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Fail** Windscreen washer provides insufficient washer liquid (3.5 (a)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #1	2021-08-23 15:52
MOT test number	677216783650
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	25 August 2024
Full MOT history	See MOT history

Tax calculation

CarCheck.co.uk page 5/11




report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

DP18KZV

report date: 2024-03-28

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here.

Plate changes

See in this check if this HYUNDAI had different number plates.

More info >

More info >

CarCheck.co.uk page 8/11



DP18KZV report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-07-19
Last registration	2023-08-26
Complete history	See info



Registration #1	2018-07-19	27 mi
Registration #2	2021-08-23	21.736 mi
Registration #3		11,777 es
Registration #4		71,777 es
Registration #5		71,777 66
Registration #6		D.777 es

More info >

CarCheck.co.uk page 10/11



DP18KZV report date: 2024-03-28

Car features

The HYUNDAI factory car options list is only available in the premium report.	
S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle $\underline{\text{here}}.$

More info >

Safety ratings

NCAP rating	****
Adult	86%
Children	85%
Pedestrian	71%
Safety systems	71%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1850 mm
Height	1645 mm
Length	4475 mm
Wheel base	2670 mm
Kerb weight	1464 kg
Max. allowed weight	1895 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1