



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	AMICA GSI
Colour	Black
Year of manufacture	2006
Top speed	91 mph
0 - 60 mph	15.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	62 BHP
Max. torque	97 Nm at 3.000 rpm
Engine capacity	1.086 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	52.3 mpg
CO2 emission	128 g/km
CO2 label	D





Internet history

Entry 2

Date	2021-07-10
Pictures	2
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-01
Pictures	2
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-05-25
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	44
Total items failed	10

MOT #22	2023-05-22 14:45
MOT test number	733093966617
Result	✓ Passed
Next expiry date	2024-05-25
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #21	2022-05-26 16:09
MOT test number	326029670652
Result	✓ Passed
Advice	Front Exhaust silencer slightly loose (Flexi deteriorated) (8.1.1 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Inner Play in steering rack inner joint(s)
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Central Exhaust has a minor leak of exhaust gases (pipe) (6.1.2 (a))

**MOT #20**

2022-05-26 16:09

MOT test number

123360811229

Result**✗ Failed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Exhaust silencer slightly loose (Flexi deteriorated) (8.1.1 (b) (i))**Advice** Nearside Front Inner Play in steering rack inner joint(s)**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Central Exhaust has a minor leak of exhaust gases (pipe) (6.1.2 (a))**MOT #19**

2021-07-07 16:26

MOT test number

454100439965

Result**✓ Passed****Advice** Offside Suspension component mounting prescribed area is corroded but not considered excessive Inner + outer sill (5.3.6 (a) (i))**Advice** Slight play in near side front steering rack joint**Advice** Nearside Suspension component mounting prescribed area is corroded but not considered excessive Inner + outer sill (5.3.6 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** General corrosion**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #18**

2020-08-21 10:26

MOT test number

515693380538

Result**✓ Passed****Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #17**

2020-08-18 13:39

MOT test number

127903092601

Result**✗ Failed**

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Nearside Front Wheel bearing so rough it is likely to overheat or break up (5.1.3 (b) (ii))

MOT #16

2019-07-08 15:40

MOT test number

314804394868

Result**✓ Passed**

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #15

2018-06-08 15:28

MOT test number

352457285461

Result**✓ Passed**

Advice Offside front coil spring corroded

MOT #14

2018-06-04 15:33

MOT test number

982742509026

Result**✗ Failed**

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside front coil spring corroded

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps All lamps (4.7.1 (b) (ii))

**MOT #13**

2017-06-24 11:11

MOT test number

495998406938

Result

✓ Passed

Advice Nearside Front Tyre worn close to the legal limit 2mm inner edge (4.1.E.1)**Advice** Offside Front coil spring corroded (2.4.C.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front coil spring corroded (2.4.C.1b)**MOT #12**

2017-06-24 11:11

MOT test number

183316210908

Result

✗ Failed

Pass with rectification Offside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front coil spring corroded (2.4.C.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front coil spring corroded (2.4.C.1b)**Advice** Nearside Front Tyre worn close to the legal limit 2mm inner edge (4.1.E.1)**MOT #11**

2016-06-17 15:51

MOT test number

503932301891

Result

✓ Passed

MOT #10

2015-06-24 11:08

MOT test number

225655675157

Result

✓ Passed

Notice Slight play nearside inner steering joint

**MOT #9** 2014-06-27 11:52**MOT test number** 325538974141**Result** ✓ Passed**MOT #8** 2013-09-19 09:49**MOT test number** 237152663298**Result** ✓ Passed**Notice** N/s/f tyre wear on edge..washers weak..**MOT #7** 2012-09-27 11:18**MOT test number** 339551472441**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2012-09-27 11:18**MOT test number** 649311172228**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2011-09-01 14:07**MOT test number** 996864641290**Result** ✓ Passed**MOT #4** 2011-09-01 12:29**MOT test number** 128674841272**Result** ✗ Failed**Fail** Nearside Front Seat belt damaged sufficient to obstruct correct operation of the belt (5.2.2a)**Fail** Nearside Stop lamp not working (1.2.1b)



MOT #3	2010-09-16 11:44
MOT test number	211409150272
Result	✓ Passed

MOT #2	2009-09-01 12:12
MOT test number	144734649286
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2009-09-01 12:12
MOT test number	391854749402
Result	✗ Failed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Parking brake lever has no reserve travel (3.1.6b)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
25 May 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	25 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-09-26
Last registration	2023-05-22
Complete history	See info



Registration #1	2006-09-26	6 mi
Registration #2	2009-09-01	14.007 mi
Registration #3	2010-09-16	16.573 mi
Registration #4	2011-09-01	20.955 mi
Registration #5	2011-09-01	20.955 mi
Registration #6	2012-09-27	25.359 mi
Registration #7	2013-09-19	30.407 mi
Registration #8	2014-06-27	34.023 mi
Registration #9	2015-06-24	42.902 mi
Registration #10	2016-06-17	51.371 mi
Registration #11	2017-06-24	59.141 mi
Registration #12	2017-06-24	59.141 mi
Registration #13	2018-06-24	67.912 mi
Registration #14	2019-06-24	76.683 mi
Registration #15	2020-06-24	85.454 mi
Registration #16	2021-06-24	94.225 mi
Registration #17	2022-06-24	102.996 mi
Registration #18	2023-05-22	111.767 mi
Registration #19	2023-05-22	111.767 mi
Registration #20	2023-05-22	111.767 mi
Registration #21	2023-05-22	111.767 mi
Registration #22	2023-05-22	111.767 mi
Registration #23	2023-05-22	111.767 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1525 mm
Height	1570 mm
Length	3565 mm
Wheel base	2380 mm
Kerb weight	1007 kg
Max. allowed weight	1336 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

Number of axles	2
Engine number	G4HG6M912417