

Ford



General information

Make	FORD
Model	B-MAX ZETEC
Colour	White
Year of manufacture	2013
Top speed	112 mph
0 - 100 km/h	12.1 seconds
0 - 60 mph	12.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	77 kW / 105 HP / 104 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F







Internet history


Entry 2

Date Pictures 2021-09-25

12

Listing price

View report



source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price

2021-09-23

View report

12

<section-header><section-header><section-header><section-header><section-header><text><text><text><text><text><text><text><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item>





source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-16
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	25
Total items failed	10

MOT #13	2	023-08-07 09:49
MOT test	number	495634196371
Result		✓ Passed
Next exp	iry date	2024-08-16
Advice	Offside Front Tyre worn close to legal limit/worn on edge Worn on edges (5.2.3 (e))	
Minor	Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice	Coolant level low	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Worn on edges (5.2.3 (e	2))
Advice	Items removed from driver's view prior to test	
Advice	Brake pedal wearing smooth (1.1.2 (c))	





MOT #12	2023-08-07 09:49	
MOT test number	134855726807	
Result	🗙 Failed	
Advice Items removed from driver's view prior to test		
Advice Brake pedal wearing smooth (1.1.2 (c))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge Worn on edges (5.2.3 (e))		
Minor Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))		
Pass with rectificationNearside Stop lamp(s) not working (4.3.1 (a) (ii))		
Advice Coolant level low		
Advice Offside Front Tyre worn close to legal limit/worn on edge Worn on edges (5.2.3	3 (e))	

MOT #11	2022-08-17 13:47
MOT test number	645069046354
Result	✓ Passed

MOT #10		2021-07-01 07:22
MOT test	number	786566585912
Result		✓ Passed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	



MOT #9	2021-06-30 11:40
MOT test number	230627914785
Result	🗙 Failed
Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Fail Offside Side repeater missing (4.4.1 (a) (ii))	
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

2020-07-01 15:02 567414036651

🗸 Passed

MOT test number

Result

MOT #	7	2020-07-01 07:44
MOT te	st number	389342171659
Result		🗙 Failed
Fail	Offside Side repeater missing (4.4.1 (a) (ii))	
Fail	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	

МОТ #6	2019-05-22 16:02
MOT test number	780206143261
Result	✓ Passed

MOT #5	2018-09-06 11:02
MOT test number	261092069731
Result	✓ Passed





MOT #4	2018-09-05 11:27
MOT test number	605526803874
Result	🗙 Failed
Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #3

MOT test	number	604077858395
Result		🗸 Passed
Advice	Nearside Rear rear brake fluctuating, but not excessively (3.7.B.3)	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advice	Offside Rear rear brake fluctuating, but not excessively (3.7.B.3)	

MOT #2	2017-09-01 10:31
MOT test number	307164239294
Result	× Failed
Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Advice Nearside Rear rear brake fluctuating, but not excessively (3.7.B.3)	
Fail Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.	.3.1d)
Advice Offside Rear rear brake fluctuating, but not excessively (3.7.B.3)	

MOT #1	2016-05-24 09:32
MOT test number	603353622723
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

YJ13OAE

report date: 2024-03-28

2017-09-06 07:10



Tax & MOT check

Tax due: 1 October 2024	✓ Taxed	Expires: 16 August 2024	✓ МОТ
Tax status			Valid until 1 October
Days left			155
MOT expiry date			16 August 2024
Full MOT history			See MOT history
Tax calculation			

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Number of plates Correct registration	
Number of plates Correct registration Pate since	
Rumber of plates Current registration Fals since Current registration	
Number of plates Current registration Fale since Fale since Fale since	8000-00-00





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-05-23
Last registration	2023-08-07
Complete history	See info



Registration #1	2013-05-23	25 mi
Registration #2	2016-05-24	16.167 mi
Registration #3	2017-09-01	32.527 mi
Registration #4	2017-09-06	32.527 mi
Registration #5	2018-09-05	41.080 mi
Registration #6	2018-09-06	41.080 mi
Registration #7	2019-05-22	46.045 mi
Registration #8	2020-07-01	54.156 mi
Registration #9		11.177 esi
Registration #10		11.777 esi
Registration #11		11.177 esi
Registration #12		11.177 est
Registration #13		11.177 esi
Registration #14		11.177 est
Registration #15		





Car features

S0225	Air conditioning
\$0295	
\$0482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight	
Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1208 kg
Max. allowed weight	1780 kg
Additional information	
Fuel tank capacity	48
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles CarCheck.co.uk	2 page 13/13