





report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO LIFE CDTI 16V
Colour	Silver
Year of manufacture	2009
Top speed	98 mph
0 - 60 mph	16.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	125 Nm at 4.000 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	135 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date	2021-02-05	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-04-10
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	13
Total items failed	5

MOT #14		2023-03-27 12:53
MOT test	number	177878025649
Result		✓ Passed
Next expi	ry date	2024-04-10
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Exhaust starting to corrode	
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Offside Front starting to wear inside edge	

MOT #13	2022-04-11 12:14
MOT test number	786009852050
Result	✓ Passed
MOT #12	2022-04-11 12:14
MOT tost number	121602106004

MOI #12	2022-04-11 12:14
MOT test number	121683186994
Result	★ Failed
Pass with rectification (ii))	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b)
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #112021-04-08 08:26MOT test number866289160459Result✓ PassedMOT #102020-11-05 15:04MOT test number677459960146Result✓ PassedAdviceEngine cover fitted obscuring some testable components.

MOT test number

Result

Advice Offside Front tyre cracks on outer tyre wall due to age

Advice Nearside Rear tyre cracks on outer tyre wall due to age

Advice Offside Rear tyre cracks on outer tyre wall due to age

MOT #8

MOT test number

Result

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #7

MOT test number

297511614657

Result

Advice Emission reading zero no printout

2017-11-08 17:00

297511614657

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #6	2017-11-07 08:35	
MOT test number	155727049680	
Result	★ Failed	
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail Nearside Front coil	spring broken (2.4.C.1a)	
Advice Emission reading zero no printout		
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	

MOT #5	2016-11-24 09:30
MOT test number	660704532566
Result	✓ Passed
MOT #4	2015-12-01 14:37
MOT test number	499317528189
Result	✓ Passed
MOT #3	2014-07-18 13:33
MOT test number	565619194181
Result	✓ Passed
MOT #2	2013-09-02 11:36
MOT test number	995285343295
Result	✓ Passed
MOT #1	2012-10-04 12:06
MOT test number	299348072282
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	10 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type
Damage 2
Date

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	JK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-11-26
Last registration	2023-03-27
Complete history	See info



Registration #1	2009-11-26	25 mi
Registration #2	2012-10-04	1.790 mi
Registration #3	2013-09-02	2.061 mi
Registration #4	2014-07-18	2.185 mi
Registration #5	2015-12-01	2.595 mi
Registration #6	2016-11-24	5.988 mi
Registration #7	2017-11-07	9.309 mi
Registration #8	2017-11-08	9.311 mi
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		11.177 mi
Registration #12		11.117 es
Registration #13		11.177 es
Registration #14		11.117 es
Registration #15		11.177 es

PR P. P. P.

More info >

77. 777 mg

CarCheck.co.uk page 11/12



report date: 2024-03-29

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1948 mm
Height	1624 mm
Length	4052 mm
Wheel base	2630 mm
Kerb weight	1318 kg
Max. allowed weight	1895 kg

Additional information

Fuel tank capacity	53 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	3051213

CarCheck.co.uk page 12/12