



report date: 2024-03-28

General information

Make	CITROEN
Model	DS4 HDI DSTYLE
Colour	Black
Year of manufacture	2013
Top speed	118 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	122 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-07-28
Pictures	21
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-24
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	28
Total items failed	10

MOT #13	2023-08-08 14:48
MOT test number	313170752979
Result	✓ Passed
Next expiry date	2024-08-24
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Rear Outer Brake disc worn, but not excessively Both. (1.1.14 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 3 mm (5.2.3 (e))

MOT #12	2023-08-08 13:25
MOT test number	329131362150
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 3 mm (5.2.3 (e))
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))
Fail	Offside Front Headlamp aim projected beam image is obviously incorrect Bulb in wrong.? (4.1.2 (c))
Advice	Rear Outer Brake disc worn, but not excessively Both. (1.1.14 (a) (i))
Fail	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps Both not working. (4.7.1 (b) (ii))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #11** 2022-08-16 13:53**MOT test number** 386046268676**Result** ✓ Passed**Advice** Nearside rear parking brake effort weak**Advice** Coolant leak**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #10** 2022-08-16 10:28**MOT test number** 320990734401**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside rear parking brake effort weak**Advice** Coolant leak**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #9** 2021-08-25 18:27**MOT test number** 515205524564**Result** ✓ Passed**Advice** Under tray fitted**MOT #8** 2020-11-23 12:58**MOT test number** 782960367323**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #7** 2020-11-23 10:56**MOT test number** 524506013637**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #6** 2019-05-07 11:27**MOT test number** 711741687510**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inside edge (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inside edge (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #5** 2018-05-17 14:20**MOT test number** 993932196959**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front wiper smearing slightly**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2017-05-11 10:41**MOT test number** 629482306701**Result** ✓ Passed**Advice** Service due warning**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (3.5.1i)

**MOT #3** 2017-05-09 10:18**MOT test number** 495826840563**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Service due warning**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (3.5.1i)**Fail** Registration plate lamp not working (1.1.C.1d)**MOT #2** 2016-05-10 08:08**MOT test number** 995139755281**Result** ✓ Passed**MOT #1** 2016-03-29 10:56**MOT test number** 188201110448**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
24 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	24 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-03-28
Last registration	2023-08-08
Complete history	<a href="#">See info</a>



Registration #1	2013-03-28	25 mi
Registration #2	2016-03-29	25.643 mi
Registration #3	2016-05-10	26.153 mi
Registration #4	2017-05-09	35.344 mi
Registration #5	2017-05-11	35.344 mi
Registration #6	2018-05-17	42.330 mi
Registration #7	2019-05-07	47.017 mi
Registration #8	2020-11-23	57.191 mi
Registration #9	2023-08-08	25,000 mi
Registration #10	2023-08-08	25,000 mi
Registration #11	2023-08-08	25,000 mi
Registration #12	2023-08-08	25,000 mi
Registration #13	2023-08-08	25,000 mi
Registration #14	2023-08-08	25,000 mi
Registration #15	2023-08-08	25,000 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	80%
Pedestrian	43%
Safety systems	97%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1523 mm
Length	4275 mm
Wheel base	2612 mm
Kerb weight	1320 kg
Max. allowed weight	1805 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBET0001963