





report date: 2024-03-29

General information

| Make | VAUXHALL |
|---------------------|-------------------|
| Model | MOKKA ACTIVE |
| Colour | Red |
| Year of manufacture | 2018 |
| Top speed | 119 mph |
| 0 - 60 mph | 10.1 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 138 BHP |
|-------------------------|---------------------|
| Max. torque | 200 Nm at 4.900 rpm |
| Engine capacity | 1.364 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 31.7 mpg |
| Consumption extra urban | 46.3 mpg |
| Consumption combined | 39.8 mpg |
| CO2 emission | 160 g/km |
| CO2 label | G |



CarCheck.co.uk page 1/11



LC18VYN

report date: 2024-03-29

Internet history

Entry 2

Date 2022-01-11

Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

 Date
 2021-09-21

 Pictures
 3

Listing price <u>View report</u>







source: cargurus.co.uk

CarCheck.co.uk page 2/11



2021-10-21 10:26

902064939523

✓ Passed

MOT history

MOT #3

Result

MOT test number

| MOT expiry date | 2025-04-19 |
|--------------------|------------|
| MOT pass rate | 83 % |
| MOT passed | 5 |
| Failed MOT tests | 1 |
| Total advice items | 5 |
| Total items failed | 1 |

| MOT #6 | 2024-04-06 07:59 | |
|---|-----------------------|--|
| MOT test number | 633984030891 | |
| Result | ✓ Passed | |
| Next expiry date | 2025-04-19 | |
| Advice Offside Front Suspension arm pin or bush worn but not resulting in excearm rear bush slightly cracking. (5.3.4 (a) (i)) | essive movement Lower | |
| Advice Offside Front Tyre slightly damaged/cracking or perishing Perishing on outer sidewall, also has screw in tyre. (5.2.3 (d) (ii)) | | |
| Minor Offside Front Obligatory mirror slightly damaged Mirror glass damaged. (| (3.3 (b) (i)) | |
| Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt | | |
| Advice Rear Tyre slightly damaged/cracking or perishing Both rear tyres have cracking/perishing on outer sidewall. (5.2.3 (d) (ii)) | | |

| MOT #5 | 2023-03-25 10:30 |
|-----------------|------------------|
| MOT test number | 542678392240 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2022-04-20 14:53 |
| MOT test number | 334164765326 |
| Result | ✓ Passed |
| | |

CarCheck.co.uk page 3/11



LC18VYN

report date: 2024-03-29

 MOT #2
 2021-04-08 10:28

 MOT test number
 206186180183

 Result
 ✓ Passed

 MOT #1
 2021-04-08 10:28

 MOT test number
 386235915583

 Result
 X Failed

 Pass with rectification
 Offside Rear Position lamp not working (4.2.1 (a) (ii))

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 April |
|------------------|---------------------|
| Days left | 336 |
| MOT expiry date | 19 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | I |
| First licence fee (12 months) | £ 645,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |
| | |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category

Damage 2

Date

Type

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



| Owner history | |
|--|-------------|
| For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner. | |
| ******* | |
| *************************************** | |
| | |
| 2000000 | |
| ······ | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this VAUXHALL had different number plates. | |
| Number of plates | , |
| Current registration | UK UK |
| Plate since | |
| Current registration | NIE NIE |
| Plate since | |
| | More info > |
| | More into / |
| | |
| | |

CarCheck.co.uk page 8/11



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



LC18VYN

report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2018-06-08 |
| Last registration | 2024-04-06 |
| Complete history | See info |



| Registration #1 | 2018-06-08 | 28 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-04-08 | 21.194 mi |
| Registration #3 | 2021-04-08 | 21.194 mi |
| Registration #4 | | 11.777 es |
| Registration #5 | 2021-10-21 | 24.010 mi |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | D.777 es |

More info >

CarCheck.co.uk page 10/11



Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 96% |
| Children | 90% |
| Pedestrian | 67% |
| Safety systems | 100% |
| Overall rating | 89% |
| Video | see crash video |



Dimensions & weight

| Width | 2038 mm |
|---------------------|---------|
| Height | 1658 mm |
| Length | 4275 mm |
| Wheel base | 2555 mm |
| Kerb weight | 1334 kg |
| Max. allowed weight | 1843 kg |

Additional information

| Fuel tank capacity | 53 |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Engine number | B14NET 180930184LUJ |

CarCheck.co.uk page 11/11