





report date: 2024-03-29

#### General information

Make	CITROEN
Model	DS3 DSTYLE PLUS
Colour	White
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.200 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.4 mpg
CO2 emission	136 g/km
CO2 label	E



CarCheck.co.uk page 1/12



MOT history

MOT expiry date	2025-02-23
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	36
Total items failed	2

MOT #14		2024-02-22 09:56
MOT test	number	936689576368
Result		✓ Passed
Next expiry date 2025-02-2		2025-02-23
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))		

MOT #13		2024-02-21 12:52
MOT test i	number	201788557599
Result		× Failed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened inner face	(1.1.14 (a) (ii))
MAJOR	Front Registration plate inscription illegible (0.1 (b))	
<b>MAJOR</b> (5.2.3 (d) (	Nearside Front Tyre has a cut in excess of the requirements deep enough to rei))	each the ply or cords
MAJOR	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
<b>Advice</b> (5.2.3 (e))	Offside Front Tyre worn close to legal limit/worn on edge on limit also slightly	damaged sidewall
MAJOR	Offside Front Direction indicator incorrect colour (4.4.3 (a))	
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))	
MAJOR	Nearside Front Direction indicator incorrect colour (4.4.3 (a))	

CarCheck.co.uk page 2/12



YP12NSK

report date: 2024-03-29

**MOT #12** 2023-02-22 11:50 **MOT** test number 871718735623 Result ✓ Passed **Advice** Front Direction indicator slightly discoloured (4.4.3 (a)) **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides; inner face (1.1.14 (a) (ii)) **Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b)) **Advice** Offside Front Nail in tyre Advice Front Oil leak, but not excessive engine bay (8.4.1 (a) (i)) **Advice** Front Tyre worn close to legal limit/worn on edge Both Sides (5.2.3 (e))

**MOT #11** 2023-02-22 11:50 319904144939 **MOT** test number Result **X** Failed **Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b)) **Advice** Front Oil leak, but not excessive engine bay (8.4.1 (a) (i)) Advice Offside Front Nail in tyre Advice Front Brake disc worn, pitted or scored, but not seriously weakened both sides; inner face (1.1.14 (a) (ii)) Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a)) **Advice** Front Direction indicator slightly discoloured (4.4.3 (a)) **Advice** Front Tyre worn close to legal limit/worn on edge Both Sides (5.2.3 (e))

MOT #10	2022-02-24 12:55
MOT test number	898652159380
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



YP12NSK

report date: 2024-03-29

MOT #9 2022-02-24 12:55

**MOT test number** 233772534291

**Result** X Failed

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #8 2021-02-08 13:25

MOT test number 416260092497

Result \( \sqrt{Passed} \)

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #7 2020-05-20 12:29

**MOT test number** 164375705774

Result \( \sqrt{Passed} \)

MOT #6 2020-05-20 08:21

**MOT test number** 340726099091

Result X Failed

**MAJOR** Exhaust system insecure (6.1.2 (a))

MOT #5 2019-05-22 14:14

**MOT test number** 893132104737

Result \rightarrow Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



**MOT #4** 2018-05-23 14:03

**MOT test number** 425920163356

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3 2017-05-12 10:04

MOT test number 969065816604

Result 

Passed

**Advice** Rear back box strap broken

**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)

**Advice** Offside Rear Nail in tyre

MOT #2 2016-05-06 13:01

MOT test number 546793430896

**MOT #1** 2015-05-22 08:52

**MOT test number** 537012945145

CarCheck.co.uk page 5/12



#### Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	23 February 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



YP12NSK

report date: 2024-03-29

#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history		
For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full respectively.		EN
*******		
***************************************		
	More info	
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		,
Current registration	OK SIE	
Plate since		
Current registration	UK UK	
Plate since		
	Mana infa	
	More info >	

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-05-31
Last registration	2024-02-22
Complete history	See info



Registration #1	2012-05-31	10 mi
Registration #2	2015-05-22	16.996 mi
Registration #3	2016-05-06	21.373 mi
Registration #4	2017-05-12	27.083 mi
Registration #5	2018-05-23	35.768 mi
Registration #6	2019-05-22	43.930 mi
Registration #7	2020-05-20	50.996 mi
Registration #8	2020-05-20	50.996 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es
Registration #15		

More info >

CarCheck.co.uk page 11/12



## Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



# Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1147 kg
Max. allowed weight	1554 kg

## Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	FHCA1665093

CarCheck.co.uk page 12/12