



RENAULT

PNI2UAE

report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC SL27 DCI S/R P/V
Colour	Silver
Year of manufacture	2012
Top speed	99 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.996 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-03-08
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2025-02-12
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	24
Total items failed	22

MOT #16	2024-02-13 14:16
MOT test number	880947975898
Result	✓ Passed
Next expiry date	2025-02-12
Advice	Nearside Front Wing and door damaged
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Battery light on dash showing fault
Advice	Nearside Front Inner Play in steering rack inner joint(s)

**MOT #15**

2024-02-12 14:38

MOT test number

757369626395

Result**✗ Failed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Front Wing and door damaged**Advice** Nearside Front Inner Play in steering rack inner joint(s)**Fail** Nearside Front Wheel bearing play so excessive it is likely to break up (5.1.3 (a) (ii))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Battery light on dash showing fault**MOT #14**

2023-02-13 14:39

MOT test number

799109063190

Result**✓ Passed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13**

2022-01-27 15:41

MOT test number

133515452140

Result**✓ Passed****MOT #12**

2022-01-27 15:41

MOT test number

629449475350

Result**✗ Failed****Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))

**MOT #11**

2021-07-20 14:09

MOT test number

436856291129

Result

✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #10**

2021-07-20 13:35

MOT test number

573392652329

Result

✗ Failed

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #9**

2020-07-28 15:24

MOT test number

374408530084

Result

✓ Passed

**MOT #8**

2020-03-18 14:15

MOT test number

755157432276

Result**✗ Failed**

- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
- Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Front Inner Drive shaft bearing excessively worn (6.1.7 (b) (i))

MOT #7

2019-03-21 09:45

MOT test number

844587038850

Result**✓ Passed****MOT #6**

2018-03-13 14:35

MOT test number

734504578164

Result**✓ Passed****MOT #5**

2017-03-04 14:06

MOT test number

750744040131

Result**✓ Passed**

**MOT #4** 2017-03-04 12:10**MOT test number** 893915970212**Result** ✗ Failed**Fail** Nearside Rear wheel bearing rough when rotated (2.6.1)**Fail** Nearside Rear wheel bearing has excessive play (2.6.2)**Fail** Central Stop lamp not working (1.2.1b)**MOT #3** 2016-03-19 11:38**MOT test number** 238156813173**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2016-03-19 09:28**MOT test number** 548742922333**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #1** 2015-03-12 12:14**MOT test number** 508021675011**Result** ✓ Passed**Notice** High level brake lamp not working**Notice** Nearside and offside wiper blade split at ends**Notice** Nail in nearside front tyre



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
12 February 2025

Tax status	Valid until 1 March
-------------------	---------------------

Days left	306
------------------	-----

MOT expiry date	12 February 2025
------------------------	------------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-03-19
Last registration	2024-02-13
Complete history	See info



Registration #1	2012-03-19	27 mi
Registration #2	2015-03-12	28.327 mi
Registration #3	2016-03-19	44.916 mi
Registration #4	2016-03-19	44.916 mi
Registration #5	2017-03-04	64.925 mi
Registration #6	2017-03-04	64.925 mi
Registration #7	2018-03-13	76.424 mi
Registration #8	2019-03-21	83.749 mi
Registration #9	2020-03-18	94.584 mi
Registration #10	2020-03-18	94.584 mi
Registration #11	2020-03-18	94.584 mi
Registration #12	2020-03-18	94.584 mi
Registration #13	2020-03-18	94.584 mi
Registration #14	2020-03-18	94.584 mi
Registration #15	2020-03-18	94.584 mi
Registration #16	2020-03-18	94.584 mi
Registration #17	2020-03-18	94.584 mi
Registration #18	2020-03-18	94.584 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	C018034