





General information

| Make | MINI |
|---------------------|--------------------|
| Model | MINI COOPER D ALL4 |
| Colour | Red |
| Year of manufacture | 2013 |
| Top speed | 109 mph |
| 0 - 60 mph | 11.8 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 112 BHP |
|-------------------------|---------------------|
| Max. torque | 270 Nm at 1.750 rpm |
| Engine capacity | 1.995 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 37.2 mpg |
| Consumption extra urban | 56.5 mpg |
| Consumption combined | 47.1 mpg |
| CO2 emission | 158 g/km |
| CO2 label | G |







Internet history

| Entry 2 | | |
|---------------|-------------|--|
| Date | 2021-08-17 | |
| Pictures | 26 | |
| Listing price | View report | |



source: cargurus.co.uk

| Entry 1 |
|---------|
|---------|

Date

Pictures

Listing price

2021-08-03 7


View report



source: autotrader.co.uk









MOT history

| MOT expiry date | 2024-05-15 |
|--------------------|------------|
| MOT pass rate | 89 % |
| MOT passed | 8 |
| Failed MOT tests | 1 |
| Total advice items | 6 |
| Total items failed | 1 |

| МОТ #9 | 2023-05-16 13:47 |
|------------------|------------------|
| MOT test number | 807555322247 |
| Result | ✓ Passed |
| Next expiry date | 2024-05-15 |

| MOT #8 | 2022-06-22 10:36 |
|-----------------|------------------|
| MOT test number | 182825480213 |
| Result | ✓ Passed |

| MOT #7 | 2022-06-20 12:11 |
|--|------------------|
| MOT test number | 464892800319 |
| Result | 🗙 Failed |
| Fail Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i)) | |

| МОТ #6 | 2021-08-23 12:11 |
|-----------------|------------------|
| MOT test number | 857783773959 |
| Result | ✓ Passed |



| SW13FWE | |
|------------------------|---|
| report date: 2024-03-2 | 8 |

| MOT #5 | 2020-12-18 16:46 |
|---|------------------|
| MOT test number | 962537972978 |
| Result | Passed |
| AdviceOffside Front Macpherson strut pin or bush worn but not resulting in etop mount (5.3.4 (a) (i))AdviceNearside Front Macpherson strut pin or bush worn but not resulting in top mount (5.3.4 (a) (i)) | |
| MOT #4 | 2019-12-10 10:52 |
| MOT test number | 888709050322 |
| Result | ✓ Passed |

Advice Offside Rear Seat belt slightly damaged (7.1.2 (b) (i))

| MOT #3 | 2019-01-02 14:41 |
|-----------------|------------------|
| MOT test number | 876956108417 |
| Result | ✓ Passed |

| MOT #2 | 2017-10-23 11:23 |
|-----------------------------|------------------|
| MOT test number | 927133969180 |
| Result | ✓ Passed |
| Advice Engine covers fitted | |

| MOT #1 | 2016-06-13 09:17 |
|-------------------------------------|------------------|
| MOT test number | 682649842393 |
| Result | ✓ Passed |
| Advice Front tyres wearing on edges | |
| Advice Nearside Rear Nail in tyre | |



Tax & MOT check

| Taxed Taxed Tax due: 1 November 2024 | ✓ MOT Expires: 15 May 2024 |
|---|-------------------------------------|
| Tax status | Valid until 1 November |
| Days left | 187 |
| MOT expiry date | 15 May 2024 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 49 |
|---|------------|
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPL |
| Date | |
| Date | OLE |
| Category | E.S. |
| Туре | |

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 |





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx | |
|---|-------------|
| ************ | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this MINI had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | More info > |





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 12 |
| First mileage registration | 2013-06-30 |
| Last registration | 2023-05-16 |
| Complete history | <u>See info</u> |



| Registration #1 | 2013-06-30 | 9 mi |
|------------------|------------|------------|
| Registration #2 | 2016-06-13 | 30.723 mi |
| Registration #3 | 2017-10-23 | 40.201 mi |
| Registration #4 | 2019-01-02 | 47.805 mi |
| Registration #5 | 2019-12-10 | 58.053 mi |
| Registration #6 | 2020-12-18 | 65.681 mi |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | |
| | | |
| Registration #11 | | 11.227 mi |



SW13FWE report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| S0501 | |
| \$0566 | |
| \$0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|------------------------|
| Adult | 84% |
| Children | 83% |
| Pedestrian | 63% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | <u>see crash video</u> |



| Dimensions & weight | |
|------------------------|------------------|
| Width | 1789 mm |
| Height | 1561 mm |
| Length | 4097 mm |
| Wheel base | 2595 mm |
| Max. allowed weight | 1875 kg |
| Additional information | |
| Fuel tank capacity | 47 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| | 2 |
| Number of seats | 5 |

Engine number

72778439