



report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO 2000 CDTI
Colour	White
Year of manufacture	2009
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	170 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2023-09-28
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	12
Total items failed	5

MOT #14	2022-09-29 13:25
MOT test number	442721876665
Result	✓ Passed
Next expiry date	2023-09-28
Advice	Front subframe corroded
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #13	2022-09-29 06:26
MOT test number	535983566905
Result	✗ Failed
MAJOR	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
DANGEROUS	Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Front subframe corroded
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front subframe corroded
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #12** 2021-08-06 09:41**MOT test number** 251657503608**Result** ✓ Passed**Advice** Coil spring corroded both front & rear (5.3.1 (b) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #11** 2019-12-13 11:07**MOT test number** 936196454300**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #10** 2018-12-14 09:46**MOT test number** 350460669801**Result** ✓ Passed**MOT #9** 2018-01-12 09:28**MOT test number** 249883577186**Result** ✓ Passed**MOT #8** 2017-01-27 12:36**MOT test number** 518597083941**Result** ✓ Passed**MOT #7** 2016-01-30 09:03**MOT test number** 179407976983**Result** ✓ Passed**Advice** Nearside Front windscreen damaged

**MOT #6** 2015-01-30 09:07**MOT test number** 716370235024**Result** ✓ Passed**MOT #5** 2014-02-14 12:05**MOT test number** 208445744015**Result** ✓ Passed**MOT #4** 2014-02-14 12:05**MOT test number** 215695744001**Result** ✗ Failed

- Pass with rectification** Nearside Rear Tyre has had the tread recut (4.1.D.1c)
- Pass with rectification** Offside Rear coil spring broken (2.4.C.1a)
- Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Pass with rectification** Offside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)

MOT #3 2013-02-08 12:51**MOT test number** 456829933018**Result** ✓ Passed**MOT #2** 2013-02-08 12:51**MOT test number** 126979433468**Result** ✗ Failed

- Pass with rectification** Offside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)

MOT #1 2012-02-28 14:38**MOT test number** 129539252420**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
1 October 2023

✕
MOT

Expired:
28 September 2023

Tax status	Expired at 1 October 2023
Days left	212 days too late
MOT expiry date	28 September 2023
Full MOT history	See MOT history



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	WN09ZVB
Plate since	2019-09-29
Current registration	WN09ZVB
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-04-16
Last registration	2022-09-29
Complete history	See info



Registration #1	2009-04-16	18 mi
Registration #2	2012-02-28	24.025 mi
Registration #3	2013-02-08	38.315 mi
Registration #4	2014-02-14	57.360 mi
Registration #5	2015-01-30	66.456 mi
Registration #6	2016-01-30	84.264 mi
Registration #7	2017-01-27	95.760 mi
Registration #8	2018-01-29	101.277 mi
Registration #9	2019-01-29	101.277 mi
Registration #10	2020-01-29	101.277 mi
Registration #11	2021-01-29	101.277 mi
Registration #12	2022-01-29	101.277 mi
Registration #13	2022-09-29	101.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4323 mm
Kerb weight	1210 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	3302375