



report date: 2024-03-28

General information

Make	VOLVO
Model	XC90 D5 SE LUX AWD
Colour	Grey
Year of manufacture	2011
Top speed	127 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	200 BHP
Max. torque	420 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.7 mpg
Consumption extra urban	41.5 mpg
Consumption combined	34.0 mpg
CO2 emission	219 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-06-04
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-03
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	32
Total items failed	6

MOT #14	2023-07-04 10:40
MOT test number	209177262077
Result	✓ Passed
Next expiry date	2024-07-03
Advice	Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

MOT #13	2022-05-30 12:53
MOT test number	246848948474
Result	✓ Passed
Advice	Long travel on parking brake lever
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #12	2021-06-16 16:55
MOT test number	395085318396
Result	✓ Passed
Advice	Nearside Head Light out put Slightly poor Conditions. Both Sides Sills Covers & Undertray Fitted.

**MOT #11** 2021-05-27 12:10**MOT test number** 643073367632**Result** ✗ Failed**Advice** Nearside head light out put slightly poor condition. under tray, sills covered.**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**MOT #10** 2020-11-09 17:16**MOT test number** 452279521982**Result** ✓ Passed**MOT #9** 2019-08-07 10:47**MOT test number** 305728627422**Result** ✓ Passed**MOT #8** 2018-08-24 12:32**MOT test number** 902824635276**Result** ✓ Passed**Advice** Front slight damage to lower section of number plate**MOT #7** 2017-08-09 08:30**MOT test number** 194452652718**Result** ✓ Passed**Advice** Emissions trigger point not met

**MOT #6** 2016-08-19 14:15**MOT test number** 210019284241**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn low on edges**Advice** Nearside Front Tyre worn low on edges**MOT #5** 2016-08-19 10:30**MOT test number** 554331185759**Result** ✗ Failed**Fail** Nearside Inner Rear position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Tyre worn low on edges**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn low on edges**Fail** Parking brake: efficiency below requirements (3.7.C.1b)**MOT #4** 2015-08-11 09:42**MOT test number** 326198420139**Result** ✓ Passed**Advice** Object removed from drivers view prior to test**Advice** Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)



MOT #3	2015-08-11 09:31
MOT test number	818753233693
Result	✗ Failed
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)
Advice	Object removed from drivers view prior to test
Advice	Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)

MOT #2	2014-08-14 13:17
MOT test number	896106124216
Result	✓ Passed
Notice	Damage to front number plate
Notice	Body sill covers fitted
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Front tyres worn down on outer of treads



MOT #12014-08-12 12:48

MOT test number596924924282

Result

Failed

Notice

Damage to front number plate

Fail

Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Notice

Body sill covers fitted

Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice

Engine covers fitted obscuring some components in the engine bay

Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice

Front tyres worn down on outer of treads



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
3 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	3 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 AF61NWR
Plate since	2019-09-28
Current registration	 AF61NWR
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-01
Last registration	2023-07-04
Complete history	See info



Registration #1	2011-09-01	21 mi
Registration #2	2014-08-12	41.893 mi
Registration #3	2014-08-14	41.944 mi
Registration #4	2015-08-11	57.914 mi
Registration #5	2015-08-11	57.914 mi
Registration #6	2016-08-19	75.396 mi
Registration #7	2016-08-19	75.396 mi
Registration #8	2017-08-09	93.045 mi
Registration #9	2019-05-29	101.277 mi
Registration #10	2019-05-29	101.277 mi
Registration #11	2019-05-29	101.277 mi
Registration #12	2019-05-29	101.277 mi
Registration #13	2019-05-29	101.277 mi
Registration #14	2019-05-29	101.277 mi
Registration #15	2019-05-29	101.277 mi
Registration #16	2019-05-29	101.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1784 mm
Length	4807 mm
Wheel base	2857 mm
Kerb weight	2158 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1044305