




report date: 2024-03-29

## General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Black
Year of manufacture	2012
Top speed	113 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg
CO2 emission	208 g/km
CO2 label	K





## MOT history

MOT expiry date	2021-01-11
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	5
Total items failed	8

MOT #8	2019-07-12 13:49
MOT test number	474308832689
Result	✓ Passed
Next expiry date	2021-01-11
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7	2019-07-09 13:40
MOT test number	433503450348
Result	✗ Failed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Fuel system component leaking engine bay (6.1.3 (b) (i))
Fail	Reversing lamp inoperative (4.6.1 (a))
Fail	Offside Front Suspension arm pin or bush excessively worn suspension arm rear bush (5.3.4 (a) (i))
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Fail	Nearside Front Suspension arm pin or bush excessively worn suspension arm rear bush (5.3.4 (a) (i))

MOT #6	2018-06-28 08:17
MOT test number	514268821397
Result	✓ Passed

**MOT #5** 2017-06-24 08:37**MOT test number** 872976940435**Result** ✓ Passed**MOT #4** 2016-06-28 15:52**MOT test number** 997206070358**Result** ✓ Passed**Advice** Offside Front seatbelt slightly frayed**MOT #3** 2016-06-28 15:21**MOT test number** 564286003972**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #2** 2015-10-13 08:34**MOT test number** 628059184740**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2015-10-07 14:24**MOT test number** 183494629936**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Front Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>DA620AX</b>
Plate since	2024-03-29
Current registration	 <b>DA620AX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2012-12-17
Last registration	2019-07-12
Complete history	<a href="#">See info</a>



Registration #1	2012-12-17	28 mi
Registration #2	2015-10-07	40.709 mi
Registration #3	2015-10-13	40.709 mi
Registration #4	2016-06-28	45.937 mi
Registration #5	2016-06-28	45.938 mi
Registration #6	2019-07-12	45.938 mi
Registration #7	2019-07-12	45.938 mi
Registration #8	2019-07-12	45.938 mi
Registration #9	2019-07-12	45.938 mi

More info >





Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1921 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	202373K