



STI3ZYF

report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 THP DSPORT PLUS
Colour	Black
Year of manufacture	2013
Top speed	130 mph
0 - 60 mph	7.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	156 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.1 mpg
CO2 emission	135 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-05-27
Pictures	24
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-07
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	29
Total items failed	7

MOT #12	2023-07-08 07:59
MOT test number	640371995080
Result	✓ Passed
Next expiry date	2024-07-07
Advice	Rear Exhaust silencer slightly loose rear exhaust box strap missing (8.1.1 (b) (i))
Advice	Front Exhaust mounting defective front bracket broken (6.1.2 (a))

MOT #11	2022-06-24 15:13
MOT test number	498042929656
Result	✓ Passed
Advice	Offside Rear Nail in tyre
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Nail in tyre
Advice	Rear Exhaust mounting defective (6.1.2 (a))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10**

2022-06-20 08:05

MOT test number

438075472828

Result**✗ Failed**

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Nearside Rear Nail in tyre
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Nail in tyre
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Headlamp aim too low (4.1.2 (a))

MOT #9

2021-06-26 08:37

MOT test number

724464162657

Result**✓ Passed**

- Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #8** 2021-06-26 08:37**MOT test number** 631217202381**Result** ✗ Failed**Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))**Pass with rectification** Reversing lamp inoperative (4.6.1 (a))**MOT #7** 2020-07-07 15:06**MOT test number** 450546766980**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #6** 2020-07-03 11:55**MOT test number** 803503620711**Result** ✗ Failed**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Outer band insecure (6.1.7 (g) (ii))**Fail** Offside Rear Reversing lamp inoperative (4.6.1 (a))**Fail** Central Rear Seat belt installation causes a three point belt lap section to be incorrectly positioned across the occupant (10.1 (u))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #5** 2019-04-11 13:48**MOT test number** 350647954113**Result** ✓ Passed**MOT #4** 2018-04-12 10:31**MOT test number** 416635284928**Result** ✓ Passed

**MOT #3** 2017-04-28 14:33**MOT test number** 652909385063**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**MOT #2** 2016-05-03 13:49**MOT test number** 138097297660**Result** ✓ Passed**MOT #1** 2016-05-02 13:54**MOT test number** 464587429825**Result** ✗ Failed**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure bulge in side wall (4.1.D.1b)**Advice** Nearside Rear Tyre worn close to the legal limit tyre on 2.3 mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit on 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
7 July 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	7 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-05-18
Last registration	2023-07-08
Complete history	See info



Registration #1	2013-05-18	14 mi
Registration #2	2016-05-02	34.714 mi
Registration #3	2016-05-03	34.714 mi
Registration #4	2017-04-28	41.128 mi
Registration #5	2018-04-12	45.188 mi
Registration #6	2019-04-11	50.373 mi
Registration #7	2020-07-03	54.290 mi
Registration #8	2021-05-20	55.277 mi
Registration #9	2022-05-20	55.277 mi
Registration #10	2023-05-20	55.277 mi
Registration #11	2023-05-20	55.277 mi
Registration #12	2023-05-20	55.277 mi
Registration #13	2023-05-20	55.277 mi
Registration #14	2023-05-20	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1165 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	FJBS1797627