



**DN6700Y**


report date: 2024-03-28

General information

Make	CITROEN
Model	C3 AIRCROSS PURETECH EDITION PICASSO
Colour	White
Year of manufacture	2017
Top speed	116 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	205 Nm at 1.500 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-10-02
Pictures	19
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-26
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	8
Total items failed	4

MOT #5	2023-06-21 10:17
MOT test number	941012053252
Result	✓ Passed
Next expiry date	2024-06-26

MOT #4	2022-06-27 13:57
MOT test number	550137755750
Result	✓ Passed

MOT #3	2021-11-19 14:30
MOT test number	320738590973
Result	✓ Passed

**MOT #2**

2021-11-17 16:23

**MOT test number**

449233669503

**Result****✗ Failed**

- Fail** Nearside Front Outer Tyre has ply or cords exposed on shoulder (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing across all sections (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Wheel bearing has excessive play (5.1.3 (a) (i))
- Fail** Offside Front Outer Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened also heavily lipped (1.1.14 (a) (ii))
- Fail** Exhaust system insecure (6.1.2 (a))

**MOT #1**

2020-11-16 13:04

**MOT test number**

273663253845

**Result****✓ Passed**

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened outer surface corroded and pitted (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn more outside central three quarters (5.2.3 (e))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened outer surface corroded and pitted (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn more outside central three quarters (5.2.3 (e))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
26 June 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	26 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>First licence fee (12 months)</b>	£ 210,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>DN6700Y</b>
Plate since	2019-09-29
Current registration	<b>DN6700Y</b>
Plate since	2019-09-29

More info >





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-11-30
Last registration	2023-06-21
Complete history	<a href="#">See info</a>



Registration #1	2017-11-30	20 mi
Registration #2	2020-11-16	23.037 mi
Registration #3	2021-11-17	29.498 mi
Registration #4		
Registration #5		
Registration #6		
Registration #7		

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	81%
Children	76%
Pedestrian	43%
Safety systems	40%
Overall rating	68%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1766 mm
Height	1631 mm
Length	4078 mm
Wheel base	2540 mm
Kerb weight	1240 kg
Max. allowed weight	1760 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	XVA30714560