





report date: 2024-03-29

General information

Make	HONDA
Model	ACCORD I-DTEC ES GT
Colour	Black
Year of manufacture	2009
Top speed	132 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-03

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-10-24
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	11
Total items failed	3

MOT #14	2023-10-25 13:09
MOT test number	603805036966
Result	✓ Passed
Next expiry date	2024-10-24
Advice Nearside Front Tyre worn close to legal limit/worn on	edge (5.2.3 (e))
Advice Offside Front Tyre worn close to legal limit/worn on ed	dge (5.2.3 (e))
Advice Anti-roll bar linkage ball joint has slight play All four. (5.3.4 (a) (i))

MOT #13	2022-10-10 16:07
MOT test number	954137745623
Result	✓ Passed
MOT #12	2021-08-21 15:43
MOT test number	627056445272

MOT test number	627856445373
Result	✓ Passed

Result	✓ Passed
NOT #11	2021 00 21 11 05
MOT #11	2021-08-21 11:05
MOT test number	389313048856
Result	× Failed
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))	
Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #10	2020-07-17 11:19
MOT test number	551401439042
Result	✓ Passed
Advice Front Exhaust has a minor leak of exhaust gases manifold area (6.1.2 (a))	

MOT #9	2019-07-13 08:19	
MOT test number	502639412059	
Result	✓ Passed	
MOT #8	2019-07-06 14:14	
MOT test number	287891661091	
Result	X Failed	
Fail Offside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))		

onside Front opper suspension and sun joint excessively worn (3.3.4 (a) (i))	
MOT #7	2018-07-21 09:16
MOT test number	945535772746
Result	✓ Passed
MOT #6	2017-07-11 09:48
MOT test number	209440888050
Result	✓ Passed
MOT #5	2016-08-02 09:54
MOT test number	368133447146
Result	✓ Passed
Advice Offside Rear brake sticking slightly and pads wearing unevenly	

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4 2015-03-09 11:12

MOT test number 966608965087

Result ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2014-03-10 14:48

MOT test number 536429564026

Result \sqrt{Passed}

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2013-02-20 10:49

MOT test number 549501153036

Result ✓ Passed

MOT #1 2012-02-29 11:48

MOT test number 937790062034

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	24 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

_	
Owner	hictory
OWILL	HISLOIV

For how long did the current and previous owner(s) have this HONDA? How many owner	
have? Check it in the premium report and see all owner registrations. Download the full	report <u>nere</u> .

	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
See III this check if this Honda had different humber places.	
Number of protes	
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	Mana infa
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-03-12
Last registration	2023-10-25
Complete history	See info



Registration #1	2009-03-12	10 mi
Registration #2	2012-02-29	34.392 mi
Registration #3	2013-02-20	44.931 mi
Registration #4	2014-03-10	57.463 mi
Registration #5	2015-03-09	72.619 mi
Registration #6	2016-08-02	81.693 mi
Registration #7	2017-07-11	88.772 mi
Registration #8	2018-07-21	99.769 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 11/12



report date: 2024-03-29

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4726 mm
Wheel base	2705 mm
Kerb weight	1540 kg

Additional information

Fuel tank capacity	65 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	N22B11006193

CarCheck.co.uk page 12/12