





report date: 2024-03-28

General information

Make	KIA
Model	RIO CRDI 1 ECODYNAMICS
Colour	Black
Year of manufacture	2014
Top speed	98 mph
0 - 60 mph	14.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	170 Nm at 1.500 rpm
Engine capacity	1.120 cc
Cylinders	3
Fuel type	Diesel
Consumption city	80.7 mpg
Consumption extra urban	94.2 mpg
Consumption combined	88.3 mpg
CO2 emission	85 g/km
CO2 label	A



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 2

Date	2021-02-01
Pictures	1

Pictures

Listing price View report



source: autoonline.co.uk


Entry 1

Date	2021-01-21
Pictures	18

Listing price View report









source: yesauto.com

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-10-15
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	23
Total items failed	9

MOT #11	2023-10-16 10:21
MOT test number	686074896000
Result	✓ Passed
Next expiry date 2024-10-15	
Minor Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	

	2022 10 12 00 50
MOT #10	2023-10-13 09:59
MOT test number	663943784471
Result	X Failed
Fail Nearside Front Lower Suspension arm ball joint dust cover no longer preve (5.3.4 (b) (ii))	ents the ingress of dirt
Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Minor Offside Front Windscreen damaged but not adversely affecting driver's	view (3.2 (a) (i))
Fail Offside Front Lower Suspension arm ball joint dust cover no longer preven (b) (ii))	ts the ingress of dirt (5.3.4
Fail Nearside Front Headlamp aim projected beam image is obviously incorrec (4.1.2 (c))	t Bulb not fitted correctly

MOT #9	2022-10-05 14:32
MOT test number	974752699239
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT test number

Result

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Offside drl not working

Fail Offside Windscreen washer provides insufficient washer liquid not working (3.5 (a))

MOT #7

MOT test number

584419059881

Result

✓ Passed

MOT test number

508009167257

Result

Advice Coolant low

Advice Coolant leak radiator damaged


Advice Windscreen has chip inside zone A

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-28



MOT #4	2019-04-27 10:11
MOT test number	680392029830
Result	✓ Passed
Minor Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Advice Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i)))

		2010 05 11 12 20
MOT #3		2018-05-11 13:30
MOT test	number	109492837339
Result		✓ Passed
Advice	Nearside Front Outer tyre has a chunk out of sidewall	
Advice	Nearside Rear tyre worn low on extreme edges	
Advice	Nearside Front tyre worn low on extreme outer edge	

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #2 2018-05-11 13:30

MOT test number 835721126724

Result X Failed

Advice Nearside Front tyre worn low on extreme outer edge

Advice Nearside Front Outer tyre has a chunk out of sidewall

Pass with rectification Nearside Front Inner Road wheel badly damaged rim bent away (4.2.A.1a)

Advice Nearside Rear tyre worn low on extreme edges

Pass with rectification Windscreen wiper does not clear the windscreen effectively both front (8.2.2)

Pass with rectification Nearside Front Front wheel bearing has excessive play (2.5.A.3c)

MOT #1 2017-05-22 08:16

MOT test number 464332540074

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	15 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

SP14LUY

report date: 2024-03-28

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report here. More info

Plate changes

See in this check if this KIA had different number plates.

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

*

More info >

CarCheck.co.uk page 10/13



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 11/13



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-03-24
Last registration	2023-10-16
Complete history	See info



Registration #1	2014-03-24	14 mi
Registration #2	2017-05-22	37.874 mi
Registration #3	2018-05-11	48.552 mi
Registration #4	2018-05-11	48.552 mi
Registration #5	2019-04-27	61.928 mi
Registration #6	2020-08-12	80.932 mi
Registration #7	2020-08-12	80.934 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		0.00 44
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	46%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1720 mm
Height	1455 mm
Length	4045 mm
Wheel base	2570 mm
Kerb weight	1276 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	43 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	e 13/13

Number of axles 2

Engine number D3FAEH329321