



PEUGEOT



LT60UER


report date: 2024-03-29

General information

Make	PEUGEOT
Model	RCZ THP GT
Colour	Grey
Year of manufacture	2011
Top speed	132 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	156 BHP
Max. torque	240 Nm at 1.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	38.7 mpg
CO2 emission	168 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-09-14
Pictures	42
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2022-09-12
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	31
Total items failed	7

MOT #14	2021-09-13 10:29
MOT test number	504505565580
Result	✓ Passed
Next expiry date	2022-09-12
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))
Advice	Nearside Front Road wheel slightly distorted and welding (5.2.2 (c) (i))

MOT #13	2021-09-10 17:16
MOT test number	907576618245
Result	✗ Failed
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))
Advice	Nearside Front Road wheel slightly distorted and welding (5.2.2 (c) (i))
Fail	Rear Tyre has ply or cords damaged both (5.2.3 (d) (ii))
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #12** 2020-10-14 07:47**MOT test number** 805047362322**Result** ✓ Passed

- Advice** Outer sill covers and under trays fitted to the vehicle
- Advice** Nearside Front Road wheel slightly distorted welding repairs present (5.2.2 (c) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Tested in a dirty condition
- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

MOT #11 2019-10-15 07:50**MOT test number** 280507151654**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Engine covers and under trays fitted to the vehicle.

MOT #10 2019-10-15 07:50**MOT test number** 591575888857**Result** ✗ Failed

- Advice** Engine covers and under trays fitted to the vehicle.
- Pass with rectification** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #9 2018-10-11 07:10**MOT test number** 505633026880**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #8** 2018-10-01 07:43**MOT test number** 109470438635**Result** ✗ Failed

- Fail** Offside Headlamp aim too high (4.1.2 (a))
- Fail** Oil leaking excessively from engine (8.4.1 (a) (i))

MOT #7 2017-10-11 07:44**MOT test number** 895803121393**Result** ✓ Passed

- Advice** Central Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)
- Advice** Engine oil leak
- Advice** Offside Front DRL not working

MOT #6 2017-10-11 07:44**MOT test number** 990527841904**Result** ✗ Failed

- Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Engine oil leak
- Advice** Central Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)
- Advice** Offside Front DRL not working

**MOT #5** 2016-10-20 09:56**MOT test number** 581048969046**Result** ✓ Passed

- Advice** Offside Front tyre uneven wear to tread
- Advice** Offside Rear tyre perished
- Advice** Oil leak
- Advice** Nearside Front tyre uneven wear to tread
- Advice** Nearside Rear tyre perished
- Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

MOT #4 2015-10-06 09:20**MOT test number** 287618666862**Result** ✓ Passed

- Advice** Engine oil leaks
- Advice** Engine covers and under trays fitted to the vehicle

MOT #3 2015-10-06 09:20**MOT test number** 713205522768**Result** ✗ Failed

- Advice** Engine oil leaks
- Pass with rectification** Nearside Headlamp insecure (1.7.3)
- Advice** Engine covers and under trays fitted to the vehicle

MOT #2 2014-10-29 17:03**MOT test number** 905632004380**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components



MOT #1	2013-12-11 11:03
MOT test number	949755043312
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-01-31
Last registration	2021-09-13
Complete history	See info



Registration #1	2011-01-31	19 mi
Registration #2	2013-12-11	6.173 mi
Registration #3	2014-10-29	15.354 mi
Registration #4	2015-10-06	24.847 mi
Registration #5	2015-10-06	24.847 mi
Registration #6	2016-10-20	31.333 mi
Registration #7	2017-10-11	36.334 mi
Registration #8	2017-10-11	36.334 mi
Registration #9	2019-05-20	36.334 mi
Registration #10	2019-05-20	36.334 mi
Registration #11	2019-05-20	36.334 mi
Registration #12	2019-05-20	36.334 mi
Registration #13	2019-05-20	36.334 mi
Registration #14	2019-05-20	36.334 mi
Registration #15	2019-05-20	36.334 mi
Registration #16	2019-05-20	36.334 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	82%
Children	81%
Pedestrian	53%
Safety systems	83%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	2107 mm
Height	1352 mm
Length	4290 mm
Kerb weight	1372 kg
Max. allowed weight	1760 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2

Engine number

FJBJ1126611