



HYUNDAI



SGI2LCK

report date: 2024-03-28

General information

Make	HYUNDAI
Model	I40 GDI STYLE
Colour	White
Year of manufacture	2012
Top speed	122 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	133 BHP
Max. torque	164 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	155 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-07-10
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-20
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	26
Total items failed	17

MOT #14 2023-05-12 09:59

MOT test number 148964341479

Result ✓ Passed

Next expiry date 2024-05-20

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #13 2022-05-21 11:12

MOT test number 142247214876

Result ✓ Passed

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #12 2022-05-21 10:35

MOT test number 914405809934

Result ✗ Failed

Fail Emissions not tested Lambda too high (8.2.1.2 (d))

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #11**

2021-04-26 08:56

MOT test number

795919072883

Result

✓ Passed

Advice

Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #10

2020-05-19 12:08

MOT test number

662816685471

Result

✓ Passed

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Brake pipe corroded, covered in grease or other material offside front and offside rear (1.1.11 (c))

Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #9

2020-05-15 11:05

MOT test number

157638171878

Result

✗ Failed

Fail

Nearside Front Service brake excessively fluctuating (1.2.1 (e))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail

Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Brake pipe corroded, covered in grease or other material offside front and offside rear (1.1.11 (c))

Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Fail

Offside Rear Service brake excessively fluctuating (1.2.1 (e))

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail

Rear Exhaust system insecure (6.1.2 (a))

Fail

Nearside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))

**MOT #8** 2019-05-17 10:13**MOT test number** 450125898530**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front day running lamp defective**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #7** 2019-05-13 10:56**MOT test number** 184491912582**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front day running lamp defective**MOT #6** 2018-05-11 13:53**MOT test number** 807049176497**Result** ✓ Passed

**MOT #5** 2018-05-11 10:20**MOT test number** 334684068431**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Fail** Nearside front brake excessively fluctuating (3.7.B.3)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside front brake excessively fluctuating (3.7.B.3)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 215/50/17 (4.1.D.1a)**MOT #4** 2017-05-11 09:41**MOT test number** 266543133027**Result** ✓ Passed**MOT #3** 2017-05-08 14:59**MOT test number** 603855123360**Result** ✗ Failed**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Rear Mechanical brake component has restricted free movement (3.5.1k)**Fail** Offside Rear Brake pad(s) has restricted free movement (3.5.1k)**Fail** Offside rear brake binding (3.7.B.1)



MOT #2	2016-03-25 14:14
MOT test number	335905411290
Result	✓ Passed
Advice	Off side rear arm harmonic dampers insecure
Advice	Near side rear arm harmonic dampers insecure

MOT #1	2015-03-30 12:02
MOT test number	959219585023
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
20 May 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	20 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-03-29
Last registration	2023-05-12
Complete history	See info



Registration #1	2012-03-29	11 mi
Registration #2	2015-03-30	38.022 mi
Registration #3	2016-03-25	49.573 mi
Registration #4	2017-05-08	61.433 mi
Registration #5	2017-05-11	61.435 mi
Registration #6	2018-05-11	73.639 mi
Registration #7	2018-05-11	73.639 mi
Registration #8	2019-05-13	79.282 mi
Registration #9	2019-05-13	79.282 mi
Registration #10	2019-05-13	79.282 mi
Registration #11	2019-05-13	79.282 mi
Registration #12	2019-05-13	79.282 mi
Registration #13	2019-05-13	79.282 mi
Registration #14	2019-05-13	79.282 mi
Registration #15	2019-05-13	79.282 mi
Registration #16	2019-05-13	79.282 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4740 mm
Wheel base	2770 mm
Kerb weight	1534 kg
Max. allowed weight	1980 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	G4FDBU414487