



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	AGILA SXI 16V TWINPORT
Colour	Silver
Year of manufacture	2005
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	79 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.229 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	48.7 mpg
CO2 emission	144 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-08-27
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)

**MOT history**

<b>MOT expiry date</b>	2024-05-03
<b>MOT pass rate</b>	84 %
<b>MOT passed</b>	16
<b>Failed MOT tests</b>	3
<b>Total advice items</b>	14
<b>Total items failed</b>	5

**MOT #19** 2023-05-02 08:58**MOT test number** 606326116360**Result** ✓ Passed**Next expiry date** 2024-05-03**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Macpherson strut mounting damaged but not seriously weakened play. (5.3.3 (b) (i))**MOT #18** 2022-05-04 08:11**MOT test number** 256466680489**Result** ✓ Passed**Advice** Rear Direction indicator slightly discoloured both (4.4.3 (a))**Advice** Stone chips to windscreen**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm both rear bush (5.3.4 (a) (i))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm both rear bush (5.3.4 (a) (i))**MOT #17** 2021-04-23 12:34**MOT test number** 139682267750**Result** ✓ Passed

**MOT #16** 2021-04-23 12:34**MOT test number** 412536294552**Result** ✗ Failed

**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #15** 2020-04-17 13:46**MOT test number** 943118746625**Result** ✓ Passed**MOT #14** 2020-04-17 13:46**MOT test number** 256126317119**Result** ✗ Failed

**Pass with rectification** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**Pass with rectification** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #13** 2019-04-04 13:00**MOT test number** 828389686288**Result** ✓ Passed**MOT #12** 2018-04-13 10:32**MOT test number** 559577917371**Result** ✓ Passed**MOT #11** 2017-04-03 09:23**MOT test number** 461688661718**Result** ✓ Passed

**MOT #10** 2016-04-13 13:58**MOT test number** 140856124214**Result** ✓ Passed**MOT #9** 2015-04-08 15:26**MOT test number** 316548795051**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Outer Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2014-04-03 09:28**MOT test number** 617593794081**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2014-04-03 09:22**MOT test number** 539263994073**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #6** 2013-04-11 11:55**MOT test number** 519721103126**Result** ✓ Passed



<b>MOT #5</b>	2012-04-18 09:26
---------------	------------------

<b>MOT test number</b>	987539602179
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2011-04-14 10:35
---------------	------------------

<b>MOT test number</b>	549074001196
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2010-04-16 12:54
---------------	------------------

<b>MOT test number</b>	390686500131
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2009-04-09 12:27
---------------	------------------

<b>MOT test number</b>	380219799048
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---

<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--

<b>MOT #1</b>	2008-04-08 10:23
---------------	------------------

<b>MOT test number</b>	342669998060
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
3 May 2024

Tax status		Valid until 1 September
Days left		124
MOT expiry date		3 May 2024
Full MOT history		<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-01-01
Previous owner since	2019-01-01
Number of owners	1
Current owner since	2019-01-01
Previous owner since	2019-01-01

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>RF05ZXG</b>
Plate since	2019-01-01
Current registration	 <b>RF05ZXG</b>
Plate since	2019-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-04-28
Last registration	2023-05-02
Complete history	<a href="#">See info</a>



Registration #1	2005-04-28	18 mi
Registration #2	2008-04-08	16.563 mi
Registration #3	2009-04-09	23.678 mi
Registration #4	2010-04-16	29.229 mi
Registration #5	2011-04-14	34.481 mi
Registration #6	2012-04-18	39.176 mi
Registration #7	2013-04-11	41.682 mi
Registration #8	2014-04-03	43.795 mi
Registration #9	2014-04-03	43.795 mi
Registration #10	2015-04-08	44.659 mi
Registration #11	2016-04-13	45.422 mi
Registration #12	2016-05-20	46.277 mi
Registration #13	2016-06-20	46.277 mi
Registration #14	2016-07-20	46.277 mi
Registration #15	2016-08-20	46.277 mi
Registration #16	2016-09-20	46.277 mi
Registration #17	2016-10-20	46.277 mi
Registration #18	2016-11-20	46.277 mi
Registration #19	2016-12-20	46.277 mi
Registration #20	2017-01-20	46.277 mi
Registration #21	2017-02-20	46.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1955 mm
Height	1440 mm
Length	3839 mm
Wheel base	2491 mm
Kerb weight	979 kg
Max. allowed weight	1430 kg

Additional information

Fuel tank capacity	44 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Engine number	19EJ8321