

Ford



General information

Make	FORD
Model	MONDEO TITANIUM X TDCI 140
Colour	Black
Year of manufacture	2009
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G



2021-01-31
1
View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-01-08
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	22
Total items failed	4

MOT #16	2024-01-07 10:47
MOT test number	398488962676
Result	✓ Passed
Next expiry date	2025-01-08

MOT #15	2023-01-08 10:38
MOT test number	295594057503
Result	✓ Passed

MOT #14	2022-01-05 16:21
MOT test number	712658237197
Result	✓ Passed

MOT #13	2021-01-02 15:31
MOT test number	429052587916
Result	✓ Passed

Advice Suspension arm pin or bush worn but not resulting in excessive movement both rear trailing arm (5.3.4 (a) (i))





MOT #12	2019-07-03 16:47
MOT test number	694676283450
Result	Passed
AdviceOffside Front Tyre worn close to legal limit/worn on edge 2mm bald inner edgeAdviceBoth rear tyres wearing inner edge	(5.2.3 (e))

MOT #11	2018-07-09 08:01
MOT test number	825797974552
Result	✓ Passed

MOT #10		2017-06-15 11:54
MOT test	number	298059053380
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

МОТ #9		2017-06-15 11:54
MOT test number		233801615573
Result		🗙 Failed
Pass with rectification	Nearside Rear Rear position lamp(s) not working (1.1.A.3b)	
Advice Offside Front Tyr	re worn close to the legal limit (4.1.E.1)	
Pass with rectification	Nearside Front Front position lamp(s) not working (1.1.A.3b)	
Advice Nearside Front T	yre worn close to the legal limit (4.1.E.1)	

МОТ #8	2016-06-02 13:03
MOT test number	421106688187
Result	✓ Passed





MOT #7		2016-06-02 07:56
MOT tes	t number	583550393133
Result		🗙 Failed
Fail	Nearside Rear Tyre has a lump, caused by separation or partial failure of its stru	ucture (4.1.D.1b)
MOT #6		2015-06-08 12:18
MOT tes	t number	266689155495
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Front brake pads getting low and discs corroded and ridged	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Under-trays fitted obscuring some underside components	
Notice	Both reat trailing arm bushes slightly deteriorated, but no play detected	

MOT #5 2014-06-20 11:04 **MOT test number** 939041774134 Result ✓ Passed Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) Notice Under-trays fitted obscuring some underside components Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Advice Front Brake pad(s) wearing thin (3.5.1g) Notice Engine covers fitted obscuring some components in the engine bay





MOT #4	2013-06-28 14:04
MOT test	number 468419373148
Result	✓ Passed
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3	2012-10-03 18:13
MOT test number	896867872290
Result	✓ Passed

MOT #2	2012-10-03 14:40
MOT test number	306997972217
Result	🗙 Failed
Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of	f its structure (4.1.D.1b)

MOT #1	2011-10-12 15:46
MOT test number	249855281259

Result

✓ Passed



Tax & MOT check

√ Taxed	✓ MOT
Tax due: 1 July 2024	Expires: 8 January 2025
Tax status	Valid until 1 July
Days left	62
MOT expiry date	8 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow



EO09LGC report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-04-03
Last registration	2024-01-07
Complete history	See info



Registration #1	2009-04-03	13 mi
Registration #2	2011-10-12	22.361 mi
Registration #3	2012-10-03	28.755 mi
Registration #4	2012-10-03	28.755 mi
Registration #5	2013-06-28	33.590 mi
Registration #6	2014-06-20	41.546 mi
Registration #7	2015-06-08	53.780 mi
Registration #8	2016-06-02	63.706 mi
Registration #9	2016-06-02	63.706 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi
Registration #18		11.117 esi

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Max. allowed weight	2170 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
	J
Number of seats	5

Engine number

9B03425