





report date: 2024-03-28

#### General information

Make	FORD
Model	RANGER LIMITED 4X4 DCB TDCI
Colour	Blue
Year of manufacture	2012
Top speed	10 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	148 BHP
Max. torque	375 Nm at 1.500 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	27.4 mpg
Consumption extra urban	37.2 mpg
Consumption combined	32.8 mpg
CO2 emission	224 g/km
CO2 label	K



CarCheck.co.uk page 1/10



report date: 2024-03-28

### Internet history

#### Entry 2

Date 2021-07-07

Pictures 25

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-07-06
Pictures	26

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-28

	_			
MO	1	hic	to	r\/
				ıv.
				. ,

MOT expiry date	2024-05-04
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	4
Total items failed	2

MOT #9	2023-05-05 08:32
MOT test number	341713887987
Result	<b>✓</b> Passed
Next expiry date	2024-05-04
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #8	2023-05-02 12:40
MOT test number	641951070300
Result	<b>X</b> Failed
Fail Nearside Rear Leaf spring main leaf fractured (5.3.1 (b) (ii))  Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #7	2022-05-05 16:02
MOT test number	896999188836
Result	✓ Passed
MOT #6	2021-03-26 14:26
MOT test number	400916981853
Result	✓ Passed

CarCheck.co.uk page 3/10



report date: 2024-03-28

MOT #5 2020-04-22 10:40

**MOT test number** 691468552699

**Result** ✓ Passed

MOT #4 2019-03-13 11:54

**MOT test number** 703046423276

**Result** ✓ Passed

**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #3 2017-12-22 09:13

**MOT test number** 547715405231

Result \rightarrow Passed

MOT #2 2017-12-22 09:13

**MOT test number** 345487789731

**Result** X Failed

Pass with rectification Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1 2015-12-30 12:43

**MOT test number** 913866050053

**Result** ✓ Passed

CarCheck.co.uk page 4/10



report date: 2024-03-28

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-28

_	
Owner	history
OWITCE	ilistoi y

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
manage of the same	
***************************************	
***************************************	
********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK SE
Plate since	
Current registration	NK NK
Plate since	
	More info >
	,

CarCheck.co.uk page 7/10



report date: 2024-03-28

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-12-21
Last registration	2023-05-05
Complete history	See info



Registration #1	2012-12-21	8 mi
Registration #2	2015-12-30	39.488 mi
Registration #3	2017-12-22	67.289 mi
Registration #4	2017-12-22	67.289 mi
Registration #5	2019-03-13	83.609 mi
Registration #6	2020-04-22	95.211 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		10.777 es

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-28

### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

# Safety ratings

NCAP rating	****
Adult	96%
Children	86%
Pedestrian	81%
Safety systems	71%
Overall rating	89%
Video	see crash video



# Dimensions & weight

Width	1850 mm
Height	1815 mm
Length	5359 mm
Kerb weight	2048 kg
Max. allowed weight	3200 kg

# Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles CarCheck.co.uk	2 page 10/10

**Engine number** 

CG41728