





report date: 2024-03-29

## General information

Make	TOYOTA
Model	MR2 ROADSTER
Colour	Silver
Year of manufacture	2002
Top speed	130 mph
0 - 60 mph	7.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	138 BHP
Max. torque	170 Nm at 4.400 rpm
Engine capacity	1.794 сс
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.2 mpg
CO2 emission	178 g/km
CO2 label	I



CarCheck.co.uk page 1/16



report date: 2024-03-29

## Internet history

#### Entry 1

Date 2022-04-18

Pictures 22

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/16



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-02-05
MOT pass rate	78 %
MOT passed	18
Failed MOT tests	5
Total advice items	56
Total items failed	9

MOT #23	2023-02-06 14:45
MOT test number	181505151203
Result	✓ Passed
Next expiry date	2024-02-05

MOT #22	2022-03-21 17:12
MOT test number	948074363800
Result	<b>✓</b> Passed

MOT #21	2021-05-04 10:56
MOT test number	210041862259
Result	✓ Passed

MOT #20		2020-06-12 07:49
MOT test	number	464210138979
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/16



report date: 2024-03-29

MOT #19 2019-05-24 11:33

**MOT test number** 661533886121

**Result** ✓ Passed

**Advice** Headlamp has a product on the lens but not seriously reducing light output Both sides (4.1.4 (b))

Advice Front Tyre slightly damaged/cracking or perishing Both sides (5.2.3 (d) (ii))

**Advice** Nearside Front Nail in tyre

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**MOT #18** 2019-05-23 08:23

MOT test number 425656516851

Result X Failed

Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))

Advice Headlamp has a product on the lens but not seriously reducing light output Both sides (4.1.4 (b))

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Nearside Front Nail in tyre

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Heavily worn on inner edge (5.2.3 (d) (i))

Advice Front Tyre slightly damaged/cracking or perishing Both sides (5.2.3 (d) (ii))

**MOT #17** 2018-04-13 08:20

**MOT test number** 778147820929

Result \( \sqrt{Passed} \)

**Advice** Nearside rear brake fluctuating, but not excessively (3.7.B.3)

CarCheck.co.uk page 4/16



report date: 2024-03-29

MOT #16		2017-03-31 08:54
MOT test	number	738911207244
Result		✓ Passed
Advice	Offside Front wheel bearing slightly rough when rotated	
Advice	Power steering pipe(s) or hose(s) slightly corroded (2.3.2)	

MOT #15		2016-04-12 08:42
MOT test	number	698549543913
Result		✓ Passed
Advice	Power steering pipe(s) or hose(s) slightly corroded (2.3.2)	
Advice	Offside Front slightly rough when rotated	

MOT #14	2015-04-07 09:56
MOT test number	339627295097
Result	✓ Passed
Advice Power steering pipe(s) or hose(s) slightly corroded (2.3.2)	

MOT #13	2014-03-21 08:50
MOT test number	138210384042
Result	✓ Passed
Advice Power steering pipe(s) or hose(s) slightly corroded (2.3.2)	

CarCheck.co.uk page 5/16



report date: 2024-03-29

**MOT #12** 2014-03-19 10:21 517238374015 **MOT** test number Result × Failed **Advice** Power steering pipe(s) or hose(s) slightly corroded (2.3.2) Advice Parking brake lever has little reserve travel (3.1.6b) Notice Nail in offside rear tyre Nearside rear brake excessively fluctuating (3.7.B.3) Fail **Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Notice N/S/R brake binding slightly Offside Front coil spring broken (2.4.C.1a) Fail

MOT #11

MOT test number

Result

MOT #10

MOT test number

2012-04-20 11:59

MOT test number

788171812195

Result

Advice

Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

MOT #9

MOT test number

877288402165

Result

Fail Nearside Front Macpherson strut severely distorted (2.4.G.1)

Advice Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

CarCheck.co.uk page 6/16



report date: 2024-03-29

MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Front discs worn

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #7** 2011-04-19 09:33 289289701457 **MOT** test number × Failed Result **Advice** Rear Brake pad(s) wearing thin (3.5.1g) Pass with rectification Offside Front position lamp(s) not working (1.1.A.3b) Offside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Notice Front discs worn

MOT #6		2010-04-20 14:53
MOT test	number	400610810138
Result		<b>✓</b> Passed
Advice	Offside Rear brake disc slightly pitted (3.5.1h)	
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Front brake disc slightly pitted (3.5.1h)	
Advice	Nearside Rear brake disc slightly pitted (3.5.1h)	
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front brake disc slightly pitted (3.5.1h)	

CarCheck.co.uk page 7/16



report date: 2024-03-29

MOT test number

Result

Notice Rear brake discs corroded /pads low

Notice Exhaust rattle

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #4 2008-04-04 17:09 **MOT** test number 672875798085 Result ✓ Passed Notice Exhaust rattles Advice Nearside Rear brake disc slightly pitted (3.5.1h) Advice Brake pad(s) wearing thin (3.5.1g) Advice Offside Rear brake disc slightly pitted (3.5.1h) **Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 8/16



report date: 2024-03-29

**MOT** #3 2008-04-04 16:20 **MOT** test number 671625798001 Result × Failed Fail Offside Front brake disc excessively pitted (3.5.1h) Advice Nearside Rear brake disc slightly pitted (3.5.1h) **Advice** Brake pad(s) wearing thin (3.5.1g) Fail Nearside Front brake disc excessively pitted (3.5.1h) Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) Notice Exhaust rattles **Advice** Offside Rear brake disc slightly pitted (3.5.1h) **Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #2

MOT test number

Front brake disc slightly pitted (3.5.1h)

2007-04-16 16:24

514676407190

✓ Passed

Advice Rear brake disc slightly scored (3.5.1h)

 MOT #1
 2006-04-08 11:53

 MOT test number
 710668096045

 Result
 ✓ Passed

CarCheck.co.uk page 9/16



GU02YBO report date: 2024-03-29

#### Tax & MOT check



X MOT

Tax expired: 22 March 2023

**Tax status** 

Expired:
5 February 2024

Expired at 22 March 2023

Days left 404 days too late

MOT expiry date 5 February 2024

Full MOT history See MOT history

#### Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 10/16



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 12/16



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full it		A
***************************************		
***************************************		
	More info >	
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 13/16



report date: 2024-03-29

#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 14/16



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2002-04-26
Last registration	2023-02-06
Complete history	See info



Registration #1	2002-04-26	22 mi
Registration #2	2006-04-08	32.810 mi
Registration #3	2007-04-16	40.018 mi
Registration #4	2008-04-04	45.961 mi
Registration #5	2008-04-04	45.961 mi
Registration #6	2009-04-14	51.436 mi
Registration #7	2010-04-20	57.827 mi
Registration #8	2011-04-19	63.068 mi
Registration #9	2012-04-17	69.157 mi
Registration #10	2012-04-20	69.157 mi
Registration #11	2013-04-04	75.513 mi
Registration #12	2014-03-19	78.355 mi
Registration #13		D.777 es
Registration #14		11.777 es
Registration #15		9.777 es
Registration #16		0.77 44
Registration #17		11.777 esi
Registration #18		11.777 es
Registration #19		11.777 esi
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.771 44
Registration #23		11.777 es
Registration #24		11.777 au

More info >



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Dimensions & weight

Width	1695 mm
Height	1250 mm
Length	3895 mm
Wheel base	2450 mm
Max. allowed weight	1225 kg

# Additional information

Fuel tank capacity	48
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	1ZZ1045625

CarCheck.co.uk page 16/16