



RENAULT



ROI5XZP


report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM DCI EDC
Colour	Black
Year of manufacture	2015
Top speed	118 mph
0 - 100 km/h	12.1 seconds
0 - 60 mph	12.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	81 kW / 110 HP / 110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	76.4 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	B






Internet history

Entry 1

Date	2022-02-17
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-06
MOT pass rate	54 %
MOT passed	7
Failed MOT tests	6
Total advice items	20
Total items failed	19

MOT #13	2024-03-07 14:55
MOT test number	525225016088
Result	✓ Passed
Next expiry date	2025-03-06

MOT #12	2024-03-01 11:03
MOT test number	297474672152
Result	✗ Failed
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #11	2023-02-28 16:35
MOT test number	661334000494
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2023-02-28 10:20

MOT test number

477228553195

Result**✗ Failed**

- Fail** Nearside Rear Brake lever has restricted free movement calliper (1.1.15 (e))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm 2055017 (5.2.3 (e))
- Fail** Offside Rear Coil spring corroded so that its cross sectional area is reduced and seriously weakened (5.3.1 (b) (i))
- Fail** Nearside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #9

2022-02-28 09:19

MOT test number

410622292561

Result**✓ Passed****MOT #8**

2022-02-24 17:19

MOT test number

211895680514

Result**✗ Failed**

- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Heat shield loose
- Fail** Front Position lamp not working both sides (4.2.1 (a) (ii))

**MOT #7** 2021-09-27 08:55**MOT test number** 359144129923**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2021-09-27 08:32**MOT test number** 509004401797**Result** ✗ Failed**Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2020-10-06 15:23**MOT test number** 694078856061**Result** ✓ Passed**MOT #4** 2019-04-05 15:47**MOT test number** 780785903496**Result** ✓ Passed**Advice** Undertrays fitted**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Light unit cracked

**MOT #3**

2019-04-05 10:53

MOT test number

804013680226

Result**✗ Failed****Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Undertrays fitted**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Light unit cracked**MOT #2**

2018-04-25 09:46

MOT test number

785687598911

Result**✓ Passed****Advice** Nearside Front Tyre has small cut on outer sidewall**Advice** Undertrays fitted**MOT #1**

2018-04-25 09:11

MOT test number

358103444714

Result**✗ Failed****Advice** Nearside Front Tyre has small cut on outer sidewall**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Undertrays fitted**Fail** Nearside Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
6 March 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	6 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2015-05-21
Last registration	2024-03-07
Complete history	See info



Registration #1	2015-05-21	14 mi
Registration #2	2018-04-25	38.815 mi
Registration #3	2018-04-25	38.815 mi
Registration #4	2019-04-05	54.193 mi
Registration #5	2019-04-05	54.195 mi
Registration #6	2020-10-06	78.892 mi
Registration #7	2021-09-27	101.649 mi
Registration #8	2021-09-27	101.649 mi
Registration #9	2022-05-20	121.277 mi
Registration #10	2022-05-20	121.277 mi
Registration #11	2022-05-20	121.277 mi
Registration #12	2022-05-20	121.277 mi
Registration #13	2022-05-20	121.277 mi
Registration #14	2022-05-20	121.277 mi
Registration #15	2024-03-07	141.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	83%
Children	78%
Pedestrian	60%
Safety systems	56%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1804 mm
Height	1507 mm
Length	4559 mm
Wheel base	2701 mm
Kerb weight	1289 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D182616