



report date: 2024-03-28

General information

Make	FORD
Model	S-MAX TITANIUM
Colour	Black
Year of manufacture	2010
Top speed	121 mph
0 - 60 mph	9.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	144 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg
CO2 emission	189 g/km
CO2 label	J





Internet history

Entry 2

Date	2023-06-02
Pictures	31
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-08-28
Pictures	29
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-06-06
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	42
Total items failed	5

MOT #14	2023-06-07 15:00
MOT test number	792695539711
Result	✓ Passed
Next expiry date	2024-06-06

MOT #13	2022-10-03 16:34
MOT test number	438382531182
Result	✓ Passed
Advice	Rear trailing arm bushes are starting to deteriorate.
Advice	Front Brake pad(s) wearing thin approx 70% worn. (1.1.13 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12	2021-09-10 12:33
MOT test number	985591188448
Result	✓ Passed

MOT #11	2020-10-03 11:38
MOT test number	635359890516
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #10**

2020-10-03 10:28

MOT test number

921908974359

Result

✗ Failed

Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #9**

2019-09-17 12:38

MOT test number

187261678093

Result

✓ Passed

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Exhaust heat shield insecure.**MOT #8**

2018-10-02 13:25

MOT test number

644659249456

Result

✓ Passed

Advice Off side front brake calliper/flexi brake hose/hub areas show grease contamination.**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #7**

2018-10-01 09:33

MOT test number

722694313632

Result**✗ Failed****Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice

Off side front brake calliper/flexi brake hose/hub areas show grease contamination.

Fail

Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice

Near side front outer constant velocity joint gaiter split.

MOT #6

2017-09-19 14:39

MOT test number

965097558015

Result**✓ Passed****Advice**

Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice

Nearside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Advice

At least 1 metal mount is detached from and not supporting the exhaust system.

Advice

Rear registration plate deteriorated but not likely to be misread (6.3.1d)

Advice

Nearside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**MOT #5**

2017-09-16 12:18

MOT test number

343715765009

Result**✗ Failed****Advice**

Nearside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Advice

Off side front tyre tread is worn to the minimum depth of 1.6mm.

Advice

At least 1 metal mount is detached from and not supporting the exhaust system.

Fail

Nearside Rear coil spring broken (2.4.C.1a)

Advice

Rear registration plate deteriorated but not likely to be misread (6.3.1d)

Advice

Nearside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Advice

Off and near side front brake discs show wear/lipped edge.

Fail

Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice

Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #4

2016-09-10 13:34

MOT test number

108144160900

Result**✓ Passed****Advice**

Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice

Nearside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Advice

Front service brakes show imbalance of 15%.

Advice

Brake fluid level appears to be low.

Advice

Passenger seat(s) missing at time of test

Advice

Off side front headlamp mounting securing device missing/movement at the unit itself.

**MOT #3** 2015-09-26 13:24**MOT test number** 820492468900**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Oil level too low to register on dip stick**MOT #2** 2014-09-13 13:22**MOT test number** 846606954224**Result** ✓ Passed**Advice** Nearside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Notice** Parking brake lever shows travel.**Notice** Under-trays fitted obscuring some underside components**Notice** Off side front headlamp unit at least 1 mounting bolt missing.**Notice** Service brake pedal shows travel.**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #1** 2013-10-01 10:46**MOT test number** 608094173219**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
6 June 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	6 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EK60KBV
Plate since	2019-03-28
Current registration	EK60KBV
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-10-06
Last registration	2023-06-07
Complete history	See info



Registration #1	2010-10-06	27 mi
Registration #2	2013-10-01	27.370 mi
Registration #3	2014-09-13	35.273 mi
Registration #4	2015-09-26	41.947 mi
Registration #5	2016-09-10	49.584 mi
Registration #6	2017-09-16	56.617 mi
Registration #7	2017-09-19	56.638 mi
Registration #8	2018-10-01	63.580 mi
Registration #9	2018-10-02	63.602 mi
Registration #10	2019-09-20	70.277 mi
Registration #11	2019-09-20	70.277 mi
Registration #12	2019-09-20	70.277 mi
Registration #13	2019-09-20	70.277 mi
Registration #14	2019-09-20	70.277 mi
Registration #15	2019-09-20	70.277 mi
Registration #16	2019-09-20	70.277 mi
Registration #17	2019-09-20	70.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1840 mm
Height	1497 mm
Length	4342 mm
Wheel base	2640 mm
Kerb weight	1326 kg
Max. allowed weight	1905 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AU29117