



report date: 2024-03-29

General information

Make	FIAT
Model	GRAND PUNTO ACTIVE
Colour	Blue
Year of manufacture	2008
Top speed	96 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	64 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





MOT history

MOT expiry date	2021-01-25
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	27
Total items failed	7

MOT #13 2019-07-18 15:54

MOT test number 813457666950

Result ✓ Passed

Next expiry date 2021-01-25

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Exhaust has a minor leak of exhaust gases flexy (6.1.2 (a))

Advice Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #12 2018-07-18 13:45

MOT test number 996487683150

Result ✓ Passed

Advice Front exhaust flexy is worn and blowing

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2018-07-18 10:23

MOT test number

503033496380

Result

✗ Failed

Fail Offside Front Position lamp not working (4.2.1 (a))**Advice** Front exhaust flexy is worn and blowing**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Front Lower Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2017-07-12 08:03

MOT test number

888248164212

Result

✓ Passed

MOT #9

2017-07-11 14:19

MOT test number

442884549679

Result

✗ Failed

Fail Offside Rear Stop lamp not working (1.2.1b)**Fail** Nearside Rear Stop lamp not working (1.2.1b)**MOT #8**

2016-07-04 15:53

MOT test number

174573395448

Result

✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2016-07-04 13:56**MOT test number** 632807758358**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2015-06-29 12:54**MOT test number** 548050885173**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-07-22 12:48**MOT test number** 178013904274**Result** ✓ Passed**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Notice** Offside front tyre worn on inner edge**Advice** Offside Seat belt anchorage prescribed area is corroded but not considered excessive (5.2.6)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Nearside front tyre worn on outer edges**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Damage to nearside sill

**MOT #4** 2013-07-22 10:38**MOT test number** 197663303202**Result** ✓ Passed**Notice** Brake pad light on dash**Notice** N/s/outer sill damaged**MOT #3** 2012-07-26 10:02**MOT test number** 779698902292**Result** ✓ Passed**MOT #2** 2012-07-26 09:45**MOT test number** 509458702242**Result** ✗ Failed**Fail** Service brake: efficiency below requirements (3.7.B.7)**Notice** Advise unable to fully inspect all four inner wheel arches due to trims fitted.**MOT #1** 2011-09-29 14:11**MOT test number** 936022171283**Result** ✓ Passed**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2008-09-30
Last registration	2019-07-18
Complete history	See info



Registration #1	2008-09-30	8 mi
Registration #2	2011-09-29	30.164 mi
Registration #3	2012-07-26	35.697 mi
Registration #4	2012-07-26	35.697 mi
Registration #5	2013-07-22	43.084 mi
Registration #6	2014-07-22	51.862 mi
Registration #7	2015-06-29	56.339 mi
Registration #8	2016-06-29	56.339 mi
Registration #9	2016-06-29	56.339 mi
Registration #10	2016-06-29	56.339 mi
Registration #11	2016-06-29	56.339 mi
Registration #12	2016-06-29	56.339 mi
Registration #13	2016-06-29	56.339 mi
Registration #14	2016-06-29	56.339 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4363732