



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA S AC ECOFLEX
Colour	Blue
Year of manufacture	2012
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 4.800 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	58.9 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-05
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-05-05
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	19
Total items failed	11

MOT #13	2023-05-03 15:30
MOT test number	448146500293
Result	✓ Passed
Next expiry date	2024-05-05

MOT #12	2022-05-05 13:25
MOT test number	968474433514
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2021-05-06 13:47
MOT test number	693813363631
Result	✓ Passed

MOT #10	2021-05-06 09:20
MOT test number	710847649172
Result	✗ Failed
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #9** 2020-09-03 15:59**MOT test number** 150056159370**Result** ✗ Failed

- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))
- Advice** Brake pipe corroded, covered in grease or other material To ABS pump (1.1.11 (c))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #8 2019-06-28 13:20**MOT test number** 100967132418**Result** ✓ Passed**MOT #7** 2019-06-28 13:20**MOT test number** 216176478435**Result** ✗ Failed

- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #6 2018-06-29 14:51**MOT test number** 369489164361**Result** ✓ Passed

- Advice** Rear brake pipes have slight corrosion/pitting

**MOT #5** 2018-06-29 11:17**MOT test number** 376113123056**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Rear brake pipes have slight corrosion/pitting**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #4** 2017-06-30 11:04**MOT test number** 628838672406**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Brake pipe slightly corroded rear pips rusting (3.6.B.2c)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2017-06-30 11:04**MOT test number** 895357752302**Result** ✗ Failed**Pass with rectification** Rear Registration plate lamp does not illuminate simultaneously with the position lamps (1.1.C.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Items removed from driver's view prior to test**Advice** Brake pipe slightly corroded rear pips rusting (3.6.B.2c)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2016-07-01 10:04
MOT test number	261380569884
Result	✓ Passed
Advice	Front Items removed from driver's view prior to test
Advice	Slight rusting on rear brake pips

MOT #1	2015-06-30 10:59
MOT test number	707931685178
Result	✓ Passed
Notice	Items removed from driver's view prior to test
Notice	Rear brack pips rusting



Tax & MOT check

✓
Taxed

Tax due:
1 May 2025

✓
MOT

Expires:
5 May 2024

Tax status	Valid until 1 May
Days left	368
MOT expiry date	5 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-07-06
Last registration	2023-05-03
Complete history	See info



Registration #1	2012-07-06	27 mi
Registration #2	2015-06-30	10.994 mi
Registration #3	2016-07-01	27.267 mi
Registration #4	2017-06-30	40.687 mi
Registration #5	2017-06-30	40.687 mi
Registration #6	2018-06-29	51.681 mi
Registration #7	2018-06-29	51.681 mi
Registration #8	2019-06-28	58.763 mi
Registration #9	2019-06-28	58.763 mi
Registration #10	2019-06-28	58.763 mi
Registration #11	2019-06-28	58.763 mi
Registration #12	2019-06-28	58.763 mi
Registration #13	2019-06-28	58.763 mi
Registration #14	2019-06-28	58.763 mi
Registration #15	2019-06-28	58.763 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	985 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	1112936